



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNH 363U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FACE,RR.BUMPER (SN)	BUCKLED	469.27	469.27
1	SPACER,R.RR.BUMPER SIDE (SN)	NOT NECESSARY	14.02	-
1	SPACER,L.RR.BUMPER SIDE (SN)	NECESSARY	14.02	14.02
1	REFLECTOR ASSY,R.RR (SN)	SERVICEABLE	30.37	-
2	CLIP, BUMPER (SN)	NECESSARY	3.45	3.45
1	PANEL SET,L.RR.OUTSIDE (SN)	TO REPAIR SEE LABOUR	547.42	-
1	TAILLIGHT ASSY.L (SN)	SERVICEABLE	279.97	-
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
4	SENSOR RETAINER (SN) (ADDITIONAL)	NECESSARY	72.00	72.00
			1,530.52	578.74
	<b><u>LABOUR</u></b>			
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER.		160.00	160.00
	REMOVE & RENEW RR BUMPER INCLUDING FITTINGS ON. INCLUSIVE OF THE REPAIR OF PANEL SET,L.RR.OUTSIDE.		1,000.00	650.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P)		1,500.00	520.00
			2,660.00	1,330.00
	<b>GRAND TOTAL</b>		<b>4,190.52</b>	<b>1,908.74</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>1,908.74</b>

Report Ref No. CS/SMR23006061/Kny3e2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.