

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTERGO Insurance Pte. Ltd.
8 Temasek Boulevard, #04-01 Suntec Tower Three
Singapore 038988**Our File No:** CS/EGI23006062/AVP3E2
Date: 17/07/2023**REFERENCE****Insured/Claimant:** BOON KOON HARDWARE PTE LTD **Policy No:** DMCG23004023
Date of Loss: 09/06/2023 **Nature of Claim:** OD **Claim No:** CDMCG23001413**DESCRIPTION & IDENTIFICATION OF VEHICLE****Reg No:** GZ910D
Make & Model: NISSAN NV350, 2.5 (A) **Engine No:** YD25345703A
Reg. Date: 08/04/2014 (Man. Year: 2014) **Chassis No:** JN1MC2E26Z0001873
Colour: Silver **Odometer:** 247580 km
Engine Capacity: 2488 cc
Market Value/New Car Price: S\$13,000.00
Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY****General Condition:** **Steering (Serviceable):** Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:****CONDITION OF TYRES****Front Tyre Size:** 195 R15C **Rear Tyre Size:** 195 R15C
Front Left Side: GREEN-MAX 6 mm **Rear Left Side:** GREEN-MAX 6 mm
Front Right Side: GREEN-MAX 6 mm **Rear Right Side:** GREEN-MAX 6 mm*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,185.10	13,139.10	2,046.00	13.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,240.00	2,900.00	1,340.00	31.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,425.10	16,039.10	3,386.00	17.43
Approved Total (Overridden) (S\$)		11,000.00		
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	18,625.10	10,200.00	8,425.10	45.24
+ GST 8.00/8.00% (S\$)	1,490.01	816.00	674.01	45.24
Nett Amount (S\$)	20,115.11	11,016.00	9,099.11	45.24

INSPECTION**Date of Assignment:** 15/06/2023
Date Inspected: 21/06/2023 **Inspected At:** J-mart Motor Pte Ltd (HQ)
Blk 5 Defu Lane 10, #01-578
Singapore 539186
Estimated Period of Repair: 12.0 days**Adjuster:** ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 17 Jul 2023)	
Parts:	N/A	NISSAN NV350 2.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GZ910D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT W/SCREEN GLASS (WCP)	Shattered	720.00 F	*720.00 F
2	1		*FRT PANEL (WCP)	Distorted	720.00 F	*720.00 F
3	1		*FRT BUMPER (WCP)	Distorted	300.00 F	*300.00 F
4	2		*FRT BUMPER RETAINER (WCP)	Damaged	200.00 F	*200.00 F
5	1		*FRT BUMPER TOW HOOK COVER (WCP)	Deformed	18.00 F	*18.00 F
6	1		*FRT BUMPER FOG LAMP (WCP)	N/S Missing / O/S NotNecessary	520.00 F	*260.00 F
7	1		*FRT BUMPER REINFORCEMENT (WCP)	Bent	360.00 F	*360.00 F
8	8		*FRT BUMPER CLIPS (WCP)	Necessary	20.00 F	*20.00 F
9	2		*HEADLAMP (WCP)	Cracked	520.00 F	*520.00 F
10	1		*FRT GRILLE (WCP)	Missing	330.00 F	*330.00 F
11	1		*FRT GRILLE LOGO (WCP)	Necessary	55.00 F	*55.00 F
12	8		*FRT GRILLE CLIPS (WCP)	Necessary	28.00 F	*28.00 F
13	1		*FRT CORNER PANEL (WCP)	N/S Dented	480.00 F	*240.00 F
14	1		*WIPER GARNISH (WCP)	Cracked	140.00 F	*140.00 F
15	1		*WIPER ARM (WCP)	Cut	70.00 F	*70.00 F
16	1		*WIPER MOTOR (WCP)	Not Necessary	260.00 F	*- F
17	1		*WIPER LINK (WCP)	Bent	300.00 F	*300.00 F
18	1		*DASHBOARD (WCP)	Cracked	900.00 F	*900.00 F
19	1		*AIR CON BLOWER ASSY (WCP)	Cracked	780.00 F	*780.00 F
20	1		*AIR CON COOLIN COIL W/HEATER (WCP)	Cracked	1,980.00 F	*1,980.00 F
21	1		*AIR CON DRYER (WCP)	Not Necessary	180.00 F	*- F
22	1		*FRT INNER PANEL (WCP)	Dented	1,080.00 F	*1,080.00 F
23	1		*INNER PANEL BRACKET (WCP)	Not Necessary	240.00 F	*- F
24	1		*INNER PANEL BEAM (WCP)	Bent	300.00 F	*300.00 F
25	1		*AIR INTAKE BOX (WCP)	Cracked	300.00 F	*300.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1		*BRAKE MASTER PUMP BRACKET (WCP)	Not Necessary	200.00 F	*- F
27	1		*CLUTCH PUMP (WCP)	Not Necessary	115.00 F	*- F
28	1		*HORN (WCP)	Not Necessary	95.00 F	*- F
29	1		*CONSOLE BOX (WCP)	Deformed	300.00 F	*300.00 F
30	1		*FRT BUMPER FOG LAMP COVERS (WCP)	N/S Missing / O/S NotNecessary	180.00 F	*90.00 F
31	1		*AIR CON DISCHARGE PIPE (WCP)	Bent	240.00 F	*240.00 F
32	1		*AIR CON SUCTION PIPE (WCP)	Bent	230.00 F	*230.00 F
33	1		*AIR CON HIGH PRESSURE PIPE (WCP)	Bent	190.00 F	*190.00 F
34	1		*AIR CON LOW PRESSURE PIPE (WCP)	Not Necessary	180.00 F	*- F
35	1		*FRT W/SCREEN GUM	Necessary	50.00 FS	*50.00 FS
36	1		*ERP BRACKET	Necessary	20.00 FS	*20.00 FS
37	1		*FRT W/SCREEN SEAL	Necessary	30.00 FS	*30.00 FS
38	1		*FRT NO PLATE	Bent	25.00 FS	*25.00 FS
39	1		*WIPER PANEL (WCP)	Distorted	360.00 F	*360.00 F
40	1		*BRAKE BOOSTER PUMP (WCP)	Dented	800.00 F	*800.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	13,816.00	11,956.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	1,369.10	1,183.10
Total Parts (\$\$)	15,185.10	13,139.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	70.00	70.00
2	PANEL BEATING	New	2,000.00	1,400.00
3	SPRAY PAINTING	New	1,600.00	1,000.00
4	REMOVE & REFIT FRT W/SCREEN	New	120.00	120.00
5	REMOVE & REFIT DASHBOARD	New	300.00	200.00
6	WIRING	New	30.00	30.00
7	TOP UP GAS	New	120.00	80.00
Gross Labour Cost (S\$)			4,240.00	2,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >