



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGA 2133Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FACE ASSY,RR.BUMPER (SN)	DEFORMED	421.50	421.50
1	SPOILER ASSY,R.RR. (SN)	SCRATCHED	79.20	79.20
1	SPACERR.RR.BUMPER SIDE (SN)	NECESSARY	15.30	15.30
7	CLIP.BUMPER (SN)	NECESSARY	12.07	12.07
1	PANEL SET,R.RR.OUTSIDE (SN)	TO REPAIR SEE LABOUR	750.82	-
1	LIGHT ASSY,R.TAIL (SN)	BROKEN	672.90	672.90
1	WHEEL,DISKAL 17X7JJ (SN)	NOT NECESSARY	678.60	-
2	RUBBERRR QTR W/SHIELD @\$7.80 (SN)	NOT NECESSARY	15.60	-
1	SEALR.QUARTER GLASS (SN)	NOT NECESSARY	28.20	-
1	CLIP AQTR. (SN)	NOT NECESSARY	2.40	-
1	CLIPQUARTER WINDSHIELD A (SN)	NOT NECESSARY	3.07	-
1	CLIPL (SN)	NOT NECESSARY	3.07	-
1	WINDSCREEN SEALANT (N) (SN)	NOT NECESSARY	60.00	-
1	SUNDRIES (SN)	NECESSARY	110.00	30.00
1	BODY JOINT SEALANT (SN)	NOT NECESSARY	120.00	-
1	SENSOR ASSY,PARKING BACK SENSOR (SN) (ADDITIONAL)	SCRATCHED	198.60	198.60
1	RETAINER,PARKING D (SN) (ADDITIONAL)	NECESSARY	33.52	33.52
1	UNDERCOVERBSI RADAR R. (SN) (ADDITIONAL)	CRACKED	40.27	40.27
1	EMBLEM,RR. (SN) (ADDITIONAL)	NECESSARY	24.90	24.90
			3,270.02	1,528.26
LABOUR				
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER.		250.00	180.00
	REMOVE & INSTALL REAR COMPARTMENT LININGS.	NOT NECESSARY	650.00	-
	REMOVE & INSTALL RIGHT REAR QUARTER GLASS.	NOT NECESSARY	480.00	-
	REMOVE & INSTALL RR R SLIDING DOOR.	NOT NECESSARY	650.00	-
	REMOVE & REPLACE RR R UNDERCARRIAGE PARTS.(N).	NOT NECESSARY	1,500.00	-
	REMOVE & TRANSFER TYRE TO NEW RIM.	NOT NECESSARY	60.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	CUT & RENEW RR R FENDER. STRAIGHTEN INNER PANEL. INCLUSIVE OF THE REPAIR OF PANEL SET,R.RR.OUTSIDE.		4,000.00	1,300.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.		3,000.00	1,560.00
	WHEEL ALIGNMENT X4.	NOT NECESSARY	220.00	-
			10,810.00	3,040.00
GRAND TOTAL			14,080.02	4,568.26
RECOMMENDED COST OF REPAIRS				4,568.26

Report Ref No. CS/SMR23006064/Rny3m4

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.