



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBK 632U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
2	VESPA FRONT SIGNAL LIGHT	BROKEN / CRACKED	130.00	130.00
1	VESPA UPPER HANDLE BAR COVER FAIRING	CRACKED	160.00	160.00
1	VESPA BOTTOM HANDLE BAR COVER FAIRING	CUT / SCRATCHED	160.00	160.00
1	VESPA HANDLE BAR	DISTORTED	140.00	140.00
2	VESPA UPPER BODY TRIMMING (CHROME)	CUT / GRAZED	170.00	170.00
2	VESPA LOWER BODY TRIMMING (CHROME)	GRAZED / CUT	200.00	200.00
1	VESPA MUDGUARD	BROKEN	180.00	180.00
1	VESPA FLOORBOARD	DISTORTED	200.00	200.00
1	VESPA FRONT PANEL COVER FAIRING (HORN COVER)	MISSING	90.00	90.00
1	VESPA COMPARTMENT COVER FAIRING (CENTER)	GRAZED / CUT / CRACKED	300.00	300.00
1	VESPA COMPARTMENT PANEL (CENTER)	GRAZED / CUT	100.00	100.00
1	VESPA STEERING CONE BEARING	NOT NECESSARY	150.00	-
1	VESPA FRONT RIM	TO REPAIR SEE LABOUR	350.00	-
1	VESPA FRONT WHEEL BEARING	NOT NECESSARY	50.00	-
1	VESPA FRONT WHEEL SEAL	NOT NECESSARY	20.00	-
1	VESPA FRONT SUSPENSION ALUMINIUM BRACKET (LEFT)	GRAZED	85.00	85.00
1	VESPA FRONT SUSPENSION	DISTORTED / GRAZED	480.00	480.00
1	VESPA BRAKE MASTER CYLINDER (RIGHT)	NOT NECESSARY	200.00	-
1	VESPA ENGINE MOUNTING (LEFT)	NOT NECESSARY	160.00	-
1	VESPA ENGINE MOUNTING FAIRING BLUE (LEFT)	NOT NECESSARY	50.00	-
2	VESPA ENGINE MOUNTING COVER MATT BLACK (LEFT)	GRAZED	50.00	50.00
2	VESPA PILLION FOOTREST	GRAZED / CUT	110.00	110.00
2	VESPA PILLION FOOTREST COVER	GRAZED	50.00	50.00
2	VESPA REAR SIGNAL LIGHT	NOT NECESSARY	130.00	-
1	VESPA FRONT BRAKE LEVER (LEFT)	GRAZED	55.00	55.00
1	VESPA REAR BRAKE LEVER (RIGHT)	BROKEN	55.00	55.00
1	VESPA REAR BRAKE CABLE	NOT NECESSARY	65.00	-
3	VESPA FRONT PANEL COVER (CHROME)	MISSING	105.00	105.00

Report Ref No. CS1/LAW23006067/Dny3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	VESPA HEADLIGHT	CRACKED	280.00	280.00
1	VESPA HEADLIGHT RIM	GRAZED / CUT	75.00	75.00
1	VESPA FRONT BRAKE DISC	NOT NECESSARY	150.00	-
1	VESPA FRONT BRAKE PAD	NOT NECESSARY	45.00	-
2	VESPA MIRROR	BENT / GRAZED	200.00	200.00
1	VESPA PIAGGIO LOGO	NECESSARY	35.00	35.00
1	VESPA MUDGUARD TRIM (CHROME)	CRACKED	45.00	45.00
1	SET VESPA GRIP	CUT	45.00	45.00
1	VESPA BOX	GRAZED	350.00	350.00
1	VESPA BOX RACK	DISTORTED	150.00	150.00
1	VESPA FLOOR BOARD COVER (MATTE BLACK)	GRAZED / CUT	45.00	45.00
1	SET VESPA FLOOR BOARD RUBBER	GRAZED / CUT	40.00	40.00
1	VESPA ENGINE COVER (SILVER) - LEFT	NOT NECESSARY	180.00	-
1	VESPA ENGINE AIR DUCT	NOT NECESSARY	45.00	-
1	VESPA SEAT UNDER COMPARTMENT TRAY (BLACK)	DEFORMED / CUT	75.00	75.00
1	VESPA MAIN STAND	GRAZED / BENT	120.00	120.00
1	VEPPA HORN	NOT NECESSARY	25.00	-
	LESS 10% DISCOUNT		-	-428.00
			5,900.00	3,852.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	TIRE FRONT (SN)	NOT NECESSARY	120.00	-
1	NUMBER PLATE (FRONT) (SN)	NECESSARY	15.00	15.00
			135.00	15.00
	<b><u>LABOUR</u></b>			
	TO REMOVE & REPLACE FRONT RIM, FRONT WHEEL BEARING, FRONT SUSPENSION, STEERING CONE, FRONT BRAKE DISC, ETC.		300.00	50.00
	TO REMOVE & REPLACE, PANEL BEATING ON THE ABOVE BODY DAMAGED PARTS, CHECK WIRING & LIGHTING SYSTEM. INCLUSIVE OF THE REPAIR OF VESPA FRONT RIM.		800.00	300.00
	TO PUTTY AND COMPLETE SPRAY PAINTING.		1,000.00	200.00
	TO CONDUCT CHASSIS ALIGNMENT.		850.00	120.00

Report Ref No. CS1/LAW23006067/Dny3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TOWING - FROM TRAFFIC POLICE COMPOUND TO WORKSHOP.		60.00	30.00
	TOWING - WORKSHOP TO ACCIDENT REPORTING CENTER.		60.00	30.00
	TOWING - ACCIDENT REPORTING CENTER TO WORKSHOP.		60.00	30.00
			3,130.00	760.00
<b>GRAND TOTAL</b>			<b>9,165.00</b>	<b>4,627.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,700.00</b>

Report Ref No. CS1/LAW23006067/Dny3e2

**ANG BRYAN TANI**

**Automotive Assessor / Investigator**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.