



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 8622S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (N)	DEEP CUT	993.40	681.20
1	FRONT LH BUMPER BRACKET (N)	CRACKED	178.60	145.80
1	FRONT LH STEP PANEL LOWER (N)	TO REPAIR SEE LABOUR	169.00	-
1	FRONT LH HEAD LAMP (N)	SCRATCHED	482.00	482.00
1	FRONT LH DOOR (N)	TO REPAIR SEE LABOUR	1,815.50	-
1	FRONT LH FRONT SPARE COOLER (N)	DENTED/BENT	1,481.00	1,121.50
	LESS 10% DISCOUNT		-	-243.05
			5,119.50	2,187.45
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
			50.00	30.00
	<u>LABOUR</u>			
	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION.		40.00	20.00
	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS. INCLUSIVE OF THE REPAIR OF FRONT LH STEP PANEL LOWER AND FRONT LH DOOR.		600.00	300.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS.		500.00	350.00
			1,140.00	670.00
	GRAND TOTAL		6,309.50	2,887.45
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,300.00

Report Ref No. CS/SMO23006068/Unp3m4

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.