

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI23006078/TVY3M4**Date:** 27/06/2023**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MQ004346
Claimant Vehicle No :	SHA6918M	Insured Vehicle No :	SFT3299J
Date of Loss:	15/06/2023	Nature of Claim:	TP
		Claim No:	M2303545

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA6918M	Engine No:	G4LEKU408923
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Chassis No:	KMHC851CVLU189907
Reg. Date:	11/03/2020 (Man. Year: 2019)	Odometer:	474178 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,864.56	1,516.32	348.24	18.68
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	800.00	660.00	140.00	17.50
Paintwork Labour	0.00	0.00	0.00	0.00
Towing	0.00	0.00	0.00	0.00
Calculated Gross Total (S\$)	2,675.56	2,187.32	488.24	18.25
Approved Total (Overridden) (S\$)		1,750.00		
(S\$)	2,675.56	1,750.00	925.56	34.59
+ GST 8.00/8.00% (S\$)	214.04	140.00	74.04	34.59
Nett Amount (S\$)	2,889.60	1,890.00	999.60	34.59

INSPECTION

Date of Assignment:	16/06/2023	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang) COMFORTDELGRO ENGINEERING PTE LTD
Date Inspected:	15/06/2023	Inspected At:	59 LOYANG DRIVE SINGAPORE 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 27 Jun 2023)**Parts:** 143 HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SHA6918M)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMBER ASSY	Deformed	459.40 FL	*459.40 FL
2	10		*REAR BUMBER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*REAR BUMBER BEAM	Not Necessary	394.80 FL	*- FL
4	1		*REAR BUMBER CENTRE MOULDING	Deformed	451.25 FL	*451.25 FL
5	1		*REAR FOG LAMP ASSY	Cut	201.50 FL	*201.50 FL
6	1		*ANTENNA SMARTKEY	Not Necessary	40.50 FL	*- FL
7	1		*REAR BUMPER MAT	Necessary	50.00 F	*50.00 F
8	1		*REAR NUMBER PLATE	Cracked	55.00 F	*55.00 F
9	1		*REAR BUMPER LOWER MOULDING	Deformed	155.00 FL	*155.00 FL
10	1		*REVERSE SENSOR	Not Working	180.00 F	*180.00 F
11	2		*REAR FENDER ADVERTISEMENT LOGO	Necessary	200.00 F	*200.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	2,209.45	1,774.15
- List Item Discount on L Items 20.00/20.00% (\$)	344.89	257.83
Total Parts (\$)	1,864.56	1,516.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
			Sub Total (\$\$)	11.00
				11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	400.00	350.00
2	SPRAY PAINT	New	300.00	250.00
3	CHECK WIRING	New	50.00	30.00
4	REMOVE/REFIX REVERSE SENSOR	New	50.00	30.00
			Gross Labour Cost (\$\$)	800.00
				660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >