

Hennessy

ASSIGNMENT

Hen

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MY
To Inspect Vehicle No: _____
at Workshop m/s Alan's
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: 500
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 891k
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 18 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: YQ 18328 Yr Regn: 10.19
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Mit Canter C.G. 2998
Colour: White A/C: Insured / Std / NI / NA
Sp. Reading: 109335 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: FEB 21 E.A 30283
Gen. Cnd: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Mod: NII / S/Rlm / STD A/Rlm or
Tyre Size: F: Mendo 195/85R15
R: Mendo (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Front Rear
R/Bal. 2 mm R/Bal. 3 3 mm
L/Bal. 2 mm L/Bal. 3 3 mm
D.O.A. 11/6/23 D.O.I. 16/6/2023
Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
Rg N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>Check re aluminium box injured how much ??</u>

Date/Time, File Pass to? ☐ : Prel. Report
☐ : Final Report

Days Of Repair: _____
Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech Invs (\$)
☐ : Weekend (\$)

Survey Fee: _____
Transportation: _____
S - RS. SI _____
P. Parts _____
Others _____

Report Format :
Lump Sum / I.B.I. (\$)

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	332C

Vehicle Details

Vehicle No.:	YQ1832Z
Vehicle to be Exported:	Yes
Intended Deregistration Date:	12 Jun 2023
Vehicle Make:	MITSUBISHI
Vehicle Model:	CANTER FEB21ER4SDEN
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	4P10D70504
Chassis No.:	FEB21EA30283
Maximum Power Output:	-
Open Market Value:	\$36,478.00
Original Registration Date:	18 Oct 2019
First Registration Date:	18 Oct 2019
Transfer Count:	1
Actual ARF Paid:	\$1,824.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	17 Oct 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$26,509.00
COE Rebate Amount:	\$16,824.00
Total Rebate Amount:	\$16,824.00

The information contained herein is correct as at 12 Jun 2023

OK

ERGO Insurance Pte. Ltd. (HQ)

INSURER:

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	023128
Policy No:	DMCG22009179	Date of Loss:	11/06/2023
Vehicle Reg. No.:	YQ1832Z	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	HTC ENGINEERING & CONSTRUCTION PTE LTD	Contact No:	+6593425990
Driver:	RABBI FAZLI		

Make/Model:	MITSUBISHI CANTER, 3.0 D FEB21ER4SDEN (M)	Vehicle Reg. Date:	18/10/2019
Vehicle Colour:	WHITE	Chassis No:	FEB21EA30283
Engine No:	4P10D70504		
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	18 ✓

*Not within
1/10/23
Penny After Pain
Ex @ 500/*

Present Location: ALAN'S UNITED AUTO PTE LTD (HQ)

COST OF CLAIMS	Amount
Parts	40,234.50
Miscellaneous Items	0.00
Labour	6,530.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	46,764.50
+ GST 8.00% (\$\$)	3,741.16
Nett Amount (\$\$)	50,505.66

This claim is handled by: CHAN YEW SIAH

REPAIR DETAILS

Reference

(Last Synchronised: 16 Jun 2023)

Part Source:

MITSUBISHI CANTER 3.0 D FEB21ER4SDEN (M) (Model not available in database)

Parts:

N/A

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: Alan's United Auto Pte Ltd/YQ1832Z/16/06/2023 09:55

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT WINDSCREEN GLASS	CM	0.00	0.00	*600.00 F ✓
2	1		*FRONT W/S GLASS RUBBER	RM	0.00	0.00	*180.00 F ✓
3	1		*FRONT DASHBOARD ASSY		0.00	0.00	*1,650.00 F ✓
4	1		*DASHBOARD LH LOWER COVER	mg cm	0.00	0.00	*280.00 F ✓
5	1		*DASHBOARD LH GROVE COVER	CM	0.00	0.00	*250.00 F ✓
6	1		*DASHBOARD LH SIDE COVER	RM	0.00	0.00	*40.00 F ✓
7	1		*INSTRUMENT PANEL REINFORCEMENT		0.00	0.00	*400.00 F ✓
8	1		*FRONT WIPER PANEL		0.00	0.00	*1,200.00 F ✓
9	1		*WIPER PANEL GARNISH	mg cm	0.00	0.00	*380.00 F ✓
10	1		*FRONT BODY PANEL	Ry	0.00	0.00	*680.00 F ✓
11	1		*CABIN ROOF PANEL	R	0.00	0.00	*1,200.00 F X
12	1		*CABIN REAR PANEL		0.00	0.00	*3,600.00 F ?
13	1		*CABIN REAR PANEL GLASS	Shorten	0.00	0.00	*190.00 F ✓
14	1		*CABIN REAR PANEL GLASS RUBBER	RM	0.00	0.00	*120.00 F ✓
15	1		*CABIN REAR LH CORNER PANEL	Ry	0.00	0.00	*350.00 F ✓
16	1		*FLOOR PANEL		0.00	0.00	*4,200.00 F ?
17	1		*FRONT LH DOOR	Ry	0.00	0.00	*1,250.00 F ✓
18	1		*FRONT LH DOOR OUTER BELT	RM	0.00	0.00	*180.00 F ✓
19	1		*FRONT LH DOOR FRONT GARNISH	mi	0.00	0.00	*60.00 F ✓
20	1		*FRONT LH DOOR CHANNEL	Di/No	0.00	0.00	*240.00 F ✓
21	1		*FRONT LH DOOR RUBBER	RM	0.00	0.00	*270.00 F ✓
22	1		*FRONT LH DOOR OUTER HANDLE	Di	0.00	0.00	*180.00 F ✓
23	1		*FRONT LH DOOR INNER LOCK	Tm	0.00	0.00	*290.00 F ✓
24	1		*FRONT LH DOOR GLASS	Ro	0.00	0.00	*330.00 F ✓
25	1		*FRONT LH DOOR GLASS REGULATOR GEAR ASSY	Ry	0.00	0.00	*750.00 F ✓
26	1		*FRONT LH DOOR INNER TRIM COVER	cm	0.00	0.00	*350.00 F ✓
27	1		*FRONT LH DOOR INNER TRIM TOP HANDLE		0.00	0.00	*185.00 F ?
28	1		*FRONT LH DOOR WINDOW SWITCH		0.00	0.00	*180.00 F ?
29	1		*FRONT LH DOOR LOWER ARCH GARNISH	RM	0.00	0.00	*95.00 F ✓
30	2		*FRONT LH DOOR HINGE	Ry	0.00	0.00	*310.00 F ✓
31	1		*FRONT LH DOOR CHECKER	Ry	0.00	0.00	*90.00 F ✓
32	1		*FRONT LH DOOR FRONT PILLAR	Ry	0.00	0.00	*1,100.00 F ✓
33	1		*FRONT LH DOOR REAR PILLAR	Ry	0.00	0.00	*900.00 F ✓
34	1		*FRONT LH STEP PANEL	RM	0.00	0.00	*300.00 F ✓
35	1		*FRONT LH STEP PANEL GARNISH	mi	0.00	0.00	*180.00 F ✓
36	1		*FRONT LH CORNER PANEL	mi	0.00	0.00	*295.00 F ✓
37	1		*FRONT LH CORNER PANEL TOP COVER	mi	0.00	0.00	*45.00 F ✓
38	1		*FRONT LH PILLAR WEATHERSTRIP	Di/No	0.00	0.00	*240.00 F ✓
39	1		*FRONT LH FENDER MUDFLAP	Di	0.00	0.00	*165.00 F ✓
40	1		*CABIN LIFTER CONTROL BAR		0.00	0.00	*650.00 F ?
41	1		*CABIN LIFTER CONTROL BAR SHAFT		0.00	0.00	*350.00 F ?
42	2		*CABIN LIFTER CONTROL BAR MOUNTING		0.00	0.00	*380.00 F ?
43	2		*CABIN LIFTER CONTROL BAR MOUNTING BRACKET		0.00	0.00	*600.00 F ?
44	1		*LH MIRROR	mi	0.00	0.00	*85.00 F ✓
45	1		*LH MIRROR BRACKET	mi Ry	0.00	0.00	*280.00 F ✓

Alan's United Auto Pte Ltd/YQ1832Z/16/06/2023 09:55. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
46	1		*LH ROUND MIRROR	M/I 0.00	0.00	*50.00 F	✓
47	1		*FRONT GRILLE ASSY	CMA 0.00	0.00	*650.00 F	✓
48	8		*FRONT GRILLE CLIP	M 0.00	0.00	*32.00 F	✓
49	1		*LH HEADLAMP	R/D 0.00	0.00	*340.00 F	✓
50	1		*LH HEADLAMP LOWER RUBBER	M/I 0.00	0.00	*18.00 F	✓
51	1		*LH HEADLAMP SIDE REFLECTOR	M/I 0.00	0.00	*145.00 F	✓
52	1		*LH SIGNAL LAMP	M/I 0.00	0.00	*240.00 F	✓
53	1		*HEADLAMP PANEL	R 0.00	0.00	*950.00 F	✓
54	1		*FRONT BUMPER	R 0.00	0.00	*580.00 F	✓
55	1		*FRONT LH BUMPER SIDE PAD	M/I 0.00	0.00	*220.00 F	✓
56	1		*FRONT LH BUMPER BRACKET	R 0.00	0.00	*150.00 F	✓
57	1		*AIR CON CONDENSER	Pu 0.00	0.00	*650.00 F	✓
58	1		*AIR CON CONDENSER BRACKET	0.00	0.00	*450.00 F	?
59	1		*AIR CON DRIER	0.00	0.00	*180.00 F	?
60	1		*AIR CON FAN COWLING	0.00	0.00	*100.00 F	?
61	1		*AIR CON FAN BLADE	0.00	0.00	*45.00 F	?
62	1		*AIR CON COOLING UNIT ASSY	CMA 0.00	0.00	*2,200.00 F	✓
63	1		*W/S GLASS WASHER TANK	0.00	0.00	*95.00 F	?
64	1		*REAR CANOPY ALUMINIUM BOX	R 0	0.00	*4,000.00 FS	?
65	1		*ERP IU BRACKET	M 0	0.00	*15.00 FS	✓
66	1		*ROOF PANEL LINING	0	0.00	*200.00 FS	?

F=Franchise part. S=SpcNett.

Sub Total (\$\$) 36,960.00
+ Margin on L,N Items 10.00% (\$\$) 3,274.50
Total Parts (\$\$) 40,234.50

Alan's United Auto Pte Ltd/YQ1832Z/16/06/2023 09:55. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No Particulars

		Lab.Type	Amount
Labour Items			
1	TO REMOVE & RENEW FRONT WINDSCRENE GLASS AND CONDUCT WATER LEAK TEST	New	150.00 ¹⁰⁰¹
2	TO REMOVE & RENEW REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	100.00 ⁵⁰¹
3	TO REMOVE ROOF LINING, FRONT SEATS, CARPET AND TRIMBOARD	New	300.00 ¹⁶⁰¹
4	TO REMOVE AIR CON CONDENSER, PIPES & DRIER, COOLING UNIT AND VACUUM AND TO RECHARGE GAS	New	200.00 ¹⁰⁰¹
5	TO REMOVE FRONT INSTRUMENT PANEL ASSY & REWIRING	New	200.00 ✓
6	TO CHECK AND ADJUST WHEEL ALIGNMENT	New	80.00 ⁶⁰¹
7	TO PUTTY AND SPRAY REPLACED PARTS	New	2,200.00 ¹⁶⁰⁰
8	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ABOVE PARTS	New	3,000.00 ²⁶⁰⁰¹
9	TO LIFT OUT CABIN FOR FACILATE REPAIR	New	300.00 ²⁰⁰¹
Gross Labour Cost (S\$)			6,530.00

Alan's United Auto Pte Ltd/YQ1832Z/16/06/2023 09:55. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >