



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7044S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER UPPER BODY	DEFORMED	2,016.00	2,016.00
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER LOWER BODY	DEFORMED	528.75	528.75
2	REAR BUMPER BRACKET LF RF @\$29.25	NOT NECESSARY	58.50	-
2	REAR BUMPER BRACKET LR RR @\$65.25	NOT NECESSARY	130.50	-
1	REAR BUMPER BEAM	NOT NECESSARY	661.50	-
	LESS 20% DISCOUNT		-683.45	-513.35
			2,733.80	2,053.40
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
1	LINE STICKER - RR RH BUMPER (SN)	NECESSARY	18.00	18.00
			68.00	68.00
<u>LABOUR</u>				
	PANEL BEATING.		800.00	400.00
	SPRAY PAINTING CHARGE.		500.00	400.00
	REMOVE/ REFIX REVERSE SENSOR.		80.00	30.00
			1,380.00	830.00
GRAND TOTAL			4,181.80	2,951.40
RECOMMENDED COST OF REPAIRS (CONFIRMED)				2,951.40

Report Ref No. NS/INC23006082/Tvp3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.