

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG23006087/UNP3M4**Date:** 10/07/2023**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30002941317
Claimant Vehicle No :	YQ1491Z	Insured Vehicle No :	YN9999P
Date of Loss:	14/06/2023	Nature of Claim:	TP
		Claim No:	318463

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YQ1491Z	Engine No:	4P10D68287
Make & Model:	MITSUBISHI CANTER, 3.0 D FEB21ER4SDEN (M)	Chassis No:	FEB21EA30209
Reg. Date:	27/08/2019 (Man. Year: 2019)	Odometer:	97666 km
Colour:	White		
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/85 R15	Rear Tyre Size:	195/85 R15 (D/D)
Front Left Side:	Delium 5 mm	Rear Left Side:	Delium 5/5 mm
Front Right Side:	Delium 5 mm	Rear Right Side:	Delium 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,513.30	1,856.10	2,657.20	58.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,260.00	770.00	490.00	38.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,773.30	2,626.10	3,147.20	54.51
Approved Total (Overridden) (S\$)		2,100.00		
Nett Amount (S\$)	5,773.30	2,100.00	3,673.30	63.63

INSPECTION

Date of Assignment:	19/06/2023		
Date Inspected:	16/06/2023	Inspected At:	LIU'S BROTHER AUTO WORK SHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTO BAY @ KAKI BUKIT SINGAPORE 417883
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 10 Jul 2023)	
Parts:	N/A	mitsubishi canter 3.0 d feb21er4sden (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YQ1491Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR	Badly Dented	2,001.50 F	*1,882.30 FL
2	1		*FRONT RH DOOR WEATHERSTRIP	Not Necessary	266.50 F	*- FL
3	1		*FRONT RH DOOR LOCK	Not Necessary	417.00 F	*- FL
4	1		*FRONT RH DOOR HINGE TOP & LOWER	Lower Bent (1Piece Only)	289.00 F	*144.50 FL
5	1		*FRONT RH DOOR CHECKERED	Serviceable	315.00 F	*- FL
6	1		*FRONT RH CORNER PANEL	Repair	486.90 F	*- FL
7	1		*FRONT RH SIGNAL LAMP	Cracked	324.30 F	*282.00 FL
8	1		*FRONT RH SIDE LAMP O/S	Broken	365.10 F	*166.00 FL
9	1		*SET FRONT RH CORNER PANEL CLIPS	Not Necessary	28.00 FS	*- FS
10	1		*SET FRONT RH SIGNAL LAMP CLIP	Not Necessary	20.00 FS	*- FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
Sub Total (\$\$)						4,513.30 2,474.80
- List Item Discount on L Items 0.00/25.00% (\$\$)						0.00 618.70
Total Parts (\$\$)						4,513.30 1,856.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	30.00	20.00
2	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS	New	600.00	300.00
3	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	600.00	420.00
4	TO APPLY RUST PROOFING , RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	30.00	30.00
Gross Labour Cost (\$\$)			1,260.00	770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >