

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XD 4278J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT CABIN REAR PANEL	REPLACED	2,660.00	2,200.00
1	FRONT CABIN REAR GLASS	REPLACED	980.00	980.00
1	FRONT CABIN REAR GLASS RUBBER	REPLACED	228.00	228.00
1	REAR LAMP RH	REPLACED	268.00	268.00
1	ROOF LINING	REPLACED	1,125.00	1,125.00
1	FRONT CABIN REAR PANEL INNER GARNISH	REPLACED	681.00	681.00
	LESS 10% DISCOUNT		-594.20	-548.20
			5,347.80	4,933.80
	<u>LABOUR</u>			
	TO DISCONNECT AND CHECK FRONT ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC. TO REMOVE AND REINSTALL DAMAGED PARTS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		50.00	20.00
	TO REMOVE AND REINSTALL FRONT CABIN REAR GLASS TO FACILITATE REPAIRS.		100.00	80.00
	TO REMOVE AND REPLACE ROOF LINING.		200.00	80.00
	TO REMOVE AND REPLACE DAMAGED PARTS AND PANELS. TO CUT, WELD, STRAIGHTEN AND PANEL BEAT WHERE NECESSARY.		880.00	580.00
	TO PUTTY AND SPRAY PAINTING ON FRONT DAMAGED PORTION INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS.		500.00	300.00
	TO APPLY RUSTPROOFING, RESEAL TUFF-COATING TREATMENT TO FRONT REPLACED / REPAIRED PARTS AND PANELS.		80.00	30.00
			1,810.00	1,090.00
	GRAND TOTAL		7,157.80	6,023.80

RECOMMENDED COST OF LUMP SUM REPAIRS	4,500.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/TPS23006095/Uvp3e2

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser