



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref: CS/TPS23006095/Uvp3e2

C/O: TOPLIS AND HARDING (S) PTE LTD  
133 CECIL STREET #17-01A KECK SENG  
TOWERSINGAPORE 069535

Date: 05/07/2023

Code: CTI

#### 1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

<b>Insured Veh.</b>	LMM 962380X	<b>Veh. Inspected</b>	XD 4278J
<b>Policy No.</b>	A330305	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	SNC23C200008	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	VICTOR (TOPLIS AND HARDING)	<b>Assign Date</b>	13/06/2023

#### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	HINO SH1EEKA	<b>c.c</b>	12913
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2010
<b>Chassis No.</b>	JHDSH1EEKXXX12207	<b>Colour</b>	WHITE
<b>Odometer</b>	542247 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	GOOD		

#### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	205/80 R22.5	HAIDA	5 mm
<b>L/H Front Tyre</b>	205/80 R22.5	HAIDA	5 mm
<b>R/H Rear Tyre</b>	205/80 R22.5 (D)	COPARTNER	5/5 mm
<b>L/H Rear Tyre</b>	205/80 R22.5 (D)	COPARTNER	5/5 mm

#### 4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.

REPAIR CONDITION SEE DETAILS.

#### 5. General Information

<b>Accident Date</b>	19/04/2023	<b>Inspection Date</b>	28/06/2023
<b>Survey held at</b>	22 TANJONG KLING ROAD SINGAPORE 628048		
<b>Repairer</b>	LIU'S BROTHER AUTO ENGINEERING WORKSHOP		

#### 5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

<b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b>	<b>5 Working Days</b>
--	-----------------------