

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	HSBC LIFE (SINGAPORE) PTE LTD		Ī	Ref:	CS3/HSB23006102/Knp3m4	
		EVARD #48-01 MARINA BAY RE TOWER 2SINGAPORE	[Date:	23/06/2023	
	ATTN: OH VALE		(Code:	HSB	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHB 6605K	Veh. Inspected		FBR 2751J	
	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
	Claim No.	S3M04NBK	Excess (\$)		0.00	
	Assign From	OH VALE	Assign Date		16/06/2023	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA SUPRA	c.c		149	
	Engine No.	HIDDEN	Year of Reg.		2020	
	Chassis No.	MH1KB2117KK088780	Colour		RED / BLACK	
	Odometer	100877 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	90/80 R17	PIRELLI		4 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	120/70 R17	PIRELLI		3 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND N/S BODY.					
5. General Information						
	Accident Date	12/06/2023	Inspect Date / T	ime	19/06/2023 (10:05 AM)	
	Survey held at	WING YAP MOTOR				
		BLK 4003 #01-114 AMK AVE 10 IND PARK 1 SINGAPORE 569624				
5a.		Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500-\$5,000					
5b.	Estimate Days of Repair					
	STIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					

Report Ref No. CS3/HSB23006102/Knp3m4

Inspected By

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser