



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNH 8596L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT DOOR RH	BENT	2,880.00	2,612.00
1	FRONT DOOR INNER TRIM BOARD RH	SERVICEABLE	2,112.00	-
1	FRONT DOOR WINDOW REGULATOR RH	DISTORTED	331.00	331.00
1	REAR DOOR RH	BENT	2,880.00	2,612.00
1	SIDE SKIRT RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT DOOR CHECKER RH (ADDITIONAL)	CRACKED/BENT	124.00	124.00
	LESS 5% DISCOUNT		-416.35	-283.95
			7,910.65	5,395.05
1	FRONT DOOR WEATHERSTRIP RH (50%) (SN)	NECESSARY	184.00	92.00
1	REAR DOOR WEATHERSTRIP RH (50%) (SN)	NECESSARY	184.00	92.00
	LESS 5% DISCOUNT		-18.40	-
			349.60	184.00
<u>SPECIAL NETT ITEMS</u>				
1	FRONT DOOR INNER TRIM BOARD CLIPS RH (SN)	NOT NECESSARY	50.00	-
1	REAR DOOR INNER TRIM BOARD CLIPS RH (SN)	NOT NECESSARY	50.00	-
1	FRONT & REAR DOOR PROTECTIVE STRIP RH (SN)	NECESSARY	100.00	60.00
			200.00	60.00
<u>LABOUR</u>				
	LABOUR CHARGES TO REMOVE, REPLACE,REFIX,REPAIR & READJUST ACCIDENT AREAS & ETC. INCLUSIVE OF THE REPAIR OF SIDE SKIRT RH.		700.00	400.00
	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT DOOR RH, REAR DOOR RH, SIDE SKIRT RH & ETC.		700.00	440.00
	LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF REAR DOOR RH.		120.00	60.00
	LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF FRONT DOOR RH.		120.00	60.00
	TO TUFF KOTE & UNDERSEAL MATERIALS.		150.00	60.00

Report Ref No. CS/AWA23006159/Kqy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING & ELECTRICAL SYSTEM.		120.00	20.00
			1,910.00	1,040.00
GRAND TOTAL			10,370.25	6,679.05
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,350.00

Report Ref No. CS/AWA23006159/Kqy3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.