

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG23006190/KPA3Q2**Date:** 11/07/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7230052417
Claimant Vehicle No :	SNC7827D	Insured Vehicle No :	SFB6999Y
Date of Loss:	17/06/2023	Nature of Claim:	TP
		Claim No:	8871492382SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNC7827D		
Make & Model:	TESLA MODEL 3 STANDARD RANGE, (A)	Engine No:	HIDDEN
Reg. Date:	16/11/2021 (Man. Year: 2021)	Chassis No:	LRW3F7FA9MC385368
Colour:	Metallic Blue	Odometer:	9218 km
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40 R19	Rear Tyre Size:	235/40 R19
Front Left Side:	Hankook 7 mm	Rear Left Side:	Hankook 7 mm
Front Right Side:	Hankook 7 mm	Rear Right Side:	Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,835.53	5,417.24	2,418.29	30.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,760.00	1,550.00	1,210.00	43.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	10,595.53	6,967.24	3,628.29	34.24
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	20/06/2023	Optima Werkz Pte Ltd (HQ) 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint Singapore 568047
Date Inspected:	19/06/2023 Inspected At:	
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP LH	Broken	1,308.41 FL	*1,308.41 FL
2	1		*FRONT HEADLAMP LOWER BRACKET LH	Bent	7.48 FL	*7.48 FL
3	1		*FRONT HEADLAMP RH	*Check	1,308.41 FL	*- FL
4	1		*FRONT HEADLAMP LOWER BRACKET RH	*Check	7.48 FL	*- FL
5	1		*FRONT BUMPER	Torn	1,214.95 FL	*1,214.95 FL
6	1		*FRONT BUMPER SIDE BRACKET LH	Missing	9.35 FL	*9.35 FL
7	1		*FRONT BUMPER SIDE BRACKET RH	Missing	9.35 FL	*9.35 FL
8	1		*FRONT BUMPER UPPER BRACKET LH	Missing	1.87 FL	*1.87 FL
9	1		*FRONT BUMPER UPPER BRACKET RH	Distorted	1.87 FL	*1.87 FL
10	1		*FRONT BUMPER INNER BRACKET LH	Cracked	12.15 FL	*12.15 FL
11	1		*FRONT BUMPER INNER BRACKET RH	*Check	12.15 FL	*- FL
12	1		*FRONT BUMPER FOG LAMP GARNISH COVER LH	Missing	6.54 FL	*6.54 FL
13	1		*FRONT BUMPER FOG LAMP GARNISH COVER RH	Missing	6.54 FL	*6.54 FL
14	1		*FRONT BUMPER TOW COVER	Missing	14.95 FL	*14.95 FL
15	1		*FRONT BUMPER LOWER GRILLE	Missing	102.80 FL	*102.80 FL
16	1		*FRONT BUMPER REINFORCEMENT	Missing	271.03 FL	*271.03 FL
17	1		*FRONT BUMPER REINFORCEMENT SUPPORT LH	Bent	52.34 FL	*52.34 FL
18	1		*FRONT BUMPER REINFORCEMENT SUPPORT RH	Bent	52.34 FL	*52.34 FL
19	1		*FRONT BUMPER LOWER REINFORCEMENT	Bent	102.80 FL	*102.80 FL
20	1		*FRONT BUMPER LOWER REINFORCEMENT SUPPORT LH	Bent	29.91 FL	*29.91 FL
21	1		*FRONT BUMPER LOWER REINFORCEMENT SUPPORT RH	*Check	29.91 FL	*- FL
22	1		*FRONT BUMPER ABSORBER FOAM	Missing	46.73 FL	*46.73 FL
23	4		*FRONT BUMPER PARKING SENSOR	Missing	654.20 FL	*654.20 FL
24	4		*FRONT BUMPER PARKING SENSOR BRACKET	Necessary	18.68 FL	*18.68 FL
25	1		*FRONT BUMPER WIRING HARNESS	*Check	93.46 FL	*- FL
26	1		*FRONT HEADLAMP WIRING HARNESS	*Check	88.79 FL	*- FL
27	1		*FRONT NUMBER PLATE HOLDER	Dented	29.91 FL	*29.91 FL
28	1		*FRONT FENDER LH	Buckled	448.60 FL	*448.60 FL
29	1		*FRONT FENDER INNER BRACKET LH	Bent	23.36 FL	*23.36 FL
30	1		*FRONT FENDER INNER SHIELD LH	Distorted	116.82 FL	*116.82 FL
31	1		*FRONT LUGGAGE COMPARTMENT	*Check	64.49 FL	*- FL
32	1		*FRONT SUPPORT PANEL	Cracked	766.36 FL	*766.36 FL
33	1		*FRONT SUPPORT PANEL BRACKET LH	Missing	7.48 FL	*7.48 FL
34	1		*FRONT SUPPORT PANEL BRACKET RH	Missing	7.48 FL	*7.48 FL
35	1		*FRONT RADAR SENSOR	Shorted	345.79 FL	*345.79 FL
36	1		*FRONT RADAR SENSOR HOLDER	Cracked	4.67 FL	*4.67 FL
37	1		*FRONT RADAR SENSOR BRACKET	Bent	7.48 FL	*7.48 FL
38	1		*FRONT COMPRESSOR BRACKET	*Check	29.91 FL	*- FL
39	1		*FRONT AIR DUCT ASSY	Distorted	186.92 FL	*186.92 FL
40	1		*FRONT AIRCON CONDENSER	*Check	420.56 FL	*- FL
41	1		*FRONT AIRCON CONDENSER FAN SHROULD ASSY	*Check	373.83 FL	*- FL
42	1		*FRONT RADIATOR	*Check	79.44 FL	*- FL
43	1		*FRONT RADIATOR FAN SHROULD ASSY	*Check	84.11 FL	*- FL
44	1		*FRONT FENDER RH (NPA)	Repair	0.00 FL	*- FL
45	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
46	1		*FRONT FENDER INNER SHIELD CLIPS LH	Necessary	40.00 FS	*40.00 FS
47	1		*FRONT NUMBER PLATE & HOLDER	Missing	50.00 FS	*45.00 FS
48	1		*RADIATOR COOLANT	*Check	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,681.70	6,004.16
- List Item Discount on L Items 10.00/10.00% (\$\$)	846.17	586.92
Total Parts (\$\$)	7,835.53	5,417.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX ,REPAIR & READJUST FRONT ACCIDENT AREAS & ETC	New	1,000.00	600.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET ,FRONT BUMPER ,FRONT FENDER LH ,FRONT FENDER RH & ETC	New	1,000.00	660.00
3	LABOUR CHARGES TO REMOVE & REPLACE FRONT BUMPER WIRING HARNESS TO EFFECT REPLACE OF FRONT BUMPER	New	120.00	60.00
4	TO REFILL AIRCON GAS & ETC (*Check)	New	120.00	0.00
5	TO TUFF KOTE & UNDERSEAL MATERIALS	New	150.00	30.00
6	TO DIAGNOSIS FAULT CODE & RESET MEMORY	New	250.00	180.00
7	TO CHECK WIRING & ELECTRICAL SYSTEM	New	120.00	20.00
Gross Labour Cost (S\$)			2,760.00	1,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >