

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 3904S

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---|---------------|-------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | TAILGATE | BENT | 3,550.00 | 2,101.00 |
| 1 | REAR BUMPER | DEFORMED | 1,085.00 | 632.70 |
| 1 | REAR BUMPER UPPER COVER | NOT NECESSARY | 388.00 | - |
| 1 | TAILGATE MOULDING | NECESSARY | 487.00 | 155.00 |
| 1 | TAILGATE INNER TRIM | NOT NECESSARY | 553.00 | - |
| 1 | TAILGATE LOCK | NOT NECESSARY | 432.00 | - |
| | LESS 15% DISCOUNT | | -974.25 | -433.31 |
| | | | 5,520.75 | 2,455.39 |
| | SPECIAL NETT ITEMS | | | |
| 1 | 8 PAX (SN) | NECESSARY | 35.00 | 10.00 |
| 1 | 70KM/H (SN) | NECESSARY | 35.00 | 10.00 |
| 1 | TAILGATE NISSAN EMBLEM (SN) | NECESSARY | 210.00 | 78.00 |
| 1 | TAILGATE NV350 EMBLEM (SN) | NECESSARY | 222.00 | 56.00 |
| 1 | TAILGATE URVAN EMBLEM (SN) | NECESSARY | 188.00 | 55.00 |
| 1 | REAR NUMBER PLATE (SN) | NOT NECESSARY | 35.00 | - |
| 1 | REVERSE SENSOR (SN) | NOT WORKING | 287.00 | 200.00 |
| | | | 1,012.00 | 409.00 |
| | <u>LABOUR</u> | | | |
| | TO REMOVE DAMAGED BODY PARTS WITH ALL NECESSARY COMPONENTS / ATTACHMENT APPLY HOTWORKS WHERE NECESSARY STRAIGHTEN FRONT FLOOR PANEL REPAIR, RESHAPE BODY DENTED PANEL IN ACCORDANCE TO FACTORY SPECIFICATIONS REPLACE NEW PARTS REFIT AND ALIGN INTO POSITION REFIT ALL NECESSARY COMPONENTS / ATTACHMENTS. | | 1,200.00 | 550.00 |
| | TO SPRAY PAINT REPLACED / REPAIRED BODY PARTS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS. | | 1,000.00 | 550.00 |
| | TO CHECK AND RECONNECT WIRING REVERSE SENSOR. | | 300.00 | 50.00 |
| | TO REMOVE AND REFIT TAILGATE WINDSCREEN. | | 150.00 | 120.00 |
| | | | 2,650.00 | 1,270.00 |
| | GRAND TOTAL | | 9,182.75 | 4,134.39 |

Report Ref No. CS/INC23006238/Rvy3e2



Page No.:2 of 2

| RECOMMENDED COST OF LUMP SUM REPAIRS | 3,300.00 |
|---|----------|
| (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED) | |

Report Ref No. CS/INC23006238/Rvy3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser