

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

idae

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 3681D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	459.40	459.40
2	REAR BUMPER SIDE BRACKET LH/RH @\$55.80	NOT NECESSARY	111.60	-
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER CENTRE MOULDING	DEFORMED	451.25	451.25
1	REAR BUMPER LOWER CENTRE MOULDING	NOT NECESSARY	155.00	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	394.80	-
2	REAR REINFORCEMENT STAY LH/RH @\$138.10	NOT NECESSARY	276.20	-
1	REAR BUMPER FOG LAMP	CUT	201.50	201.50
1	REAR SMART KEY SENSOR	NOT NECESSARY	40.50	-
1	REAR BUMPER NUMBER LAMP	NOT NECESSARY	85.30	-
1	TOWING COVER	сит	98.80	98.80
	LESS 20% DISCOUNT		-459.27	-246.59
			1,837.08	986.36
	NETT ITEMS			
1	REAR REVERSE SENSOR (N)	NOT WORKING	180.00	180.00
	LESS 10% DISCOUNT		-18.00	-18.00
			162.00	162.00
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE W/HOLDER (SN)	CUT	55.00	55.00
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
			105.00	105.00
	<u>LABOUR</u>			
	PANEL BEATING.		600.00	350.00
	SPRAY PAINTING CHARGE.		400.00	250.00
	CHECK WIRING AND LIGHTING.		60.00	30.00
	REMOVE / REFIX REVERSE SENSOR.		60.00	30.00
			1,120.00	660.00
	GRAND TOTAL		3,224.08	1,913.36

Report Ref No. NS/INC23006260/Tnp3e2





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	1,500.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)	

Report Ref No. NS/INC23006260/Tnp3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser