



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 3130C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	DEFORMED	481.10	481.10
1	FRONT BUMPER UPPER MOULDING	CUT	368.50	368.50
10	FRONT BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	FRONT BUMPER SIDE BRKT RH	DEFORMED	35.00	35.00
1	FRONT WHEEL CAP RH	CUT	346.40	346.40
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	588.80	-
1	FRONT FENDER (BLUE-DRIVE) RH	NECESSARY	26.60	26.60
1	FRONT FENDER SHIELD RH	DEFORMED	164.70	164.70
1	HEADLAMP RH	NOT NECESSARY	2,110.30	-
1	DAYLIGHT RH	NOT NECESSARY	642.50	-
1	DAYLIGHT GRILLE RH	NOT NECESSARY	93.45	-
	LESS 20% DISCOUNT		-975.87	-288.86
			3,903.48	1,155.44
	<b><u>LABOUR</u></b>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT FENDER RH.		800.00	350.00
	SPRAY PAINTING.		600.00	500.00
	CHECK WIRINGS.	NOT NECESSARY	40.00	-
	TUFF KOTE.	NOT NECESSARY	60.00	-
	WHEEL ALIGNMENT.		120.00	80.00
			1,620.00	930.00
<b>GRAND TOTAL</b>			<b>5,523.48</b>	<b>2,085.44</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>1,650.00</b>

Report Ref No. NS/INC23006261/Tvp3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.