# NCVI INVOLVING 5-TON WITH CARGO TRAILER (MID20705 & MID92842) AT OLD CHUA CHU KANG ROAD ON 25 APR 23 AT ABOUT 1715HRS




Figure A-1: Incident occurred at Old Chua Chu Kang Road. The road was narrow with a width of 2.75m per lane, with a small grass patch of 0.6m in width between the road and the guard rail.




Figure A-2: MID20705 was travelling as part of a convoy movement behind OUV MID34268




Figure A-3: A civilian truck was approaching MID 20705 in the opposite lane




Figure A-4: Both vehicles slowed down to assess the situation, with the truck coming to a stop to give way to MID 20705




Figure A-5: MID 20705 steered slight left to avoide the oncoming truck, the front left wheel rolled on the grass patch




Figure A-6: Due to soft ground, MID20705 sunk in and grazed the road guard rail



Figure B-1: Right side view of MID20705



Figure B-2: Left side view of MID20705



Figure B-3: Front view of MID20705



Figure B-4: Rear view of MID20705



Figure B-5: Close up of impact point



Figure B-6: Close up of damage on guard rail



Figure B-7: Top view of soft ground



Figure B-8: Side view of soft ground

STATEMENT OF	LCP AMIRUL HAQIM BIN RAHMAD					ALIA	SES	-			
NRIC NO	TXXXX920J	XXXX920J AGE			22			MALE/FEMALE		MALE	
EMPLOYMENT	SAF	DRIVING LICENCE NO		SAF/TI	SAF/TPT/N/02051/22		NATIONALITY		SINGAPOREAN		
DIALECT	NA	LANGUAGE SPOKEN		ENGLI	ENGLISH & MALAY		TELNO		94797179		
ADDRESS	107 YISHUN RING ROAD #06-233 760107										
INTERPRETED BY											
RECORDED BY	2LT LEE AO	2LT LEE AO RANK 2LT TIME 2300 DAT		DATE		250423	SIGN	NA			
I, LCP AMIRUL 1 Hereby write the fo On the 25th of Apri exercise. As i was p	HAQIM BIN F llowing report.	I was sup	porting	30SCE E	X Sapp	erstar f	rom Ju	ong campl	to TP 2	for thei	

DATE 250523 SIGNATURE OF DRIVERWITNESS <a href="#section-of-color: blue-state;">SIGNATURE OF DRIVERWITNESS</a>

Figure C-1: Statement of TO

EMPLOYMENT  SAF  DRIVING LICENCE NO  LANGUAGE SPOKEN  Bukit Batok East Ave 3, Bik 222, #02-142  INTERPRETED BY  RECORDED BY  2LT LEE AO XUAN  RANK  LIT  TIME  2300  DATE  250423  SIGN  NA  Time: 16.45(25/04/23) I was sitting on the front passenger seat (middle). Travelling along old cck road, me and the other veh comm saw incoming coming on the other lane and it slowed down and stopped for us to go past it, near nirvana memorial garden. Due to the narrowness of the road, TO using his judgment decided to drive slightly off the axis slowly to move forward after the incoming (opposite direction) stopped, as the incoming passenger and myself were managing the route, I was looking out in front for the TO' movement while captain Ernest was looking at the side to guide the TO and told the driver to be careful when trying to move past the incoming, but the soft ground seemed was not visible to the TO and as such the front tire sunk in. After the tire went down, me and captain Ernest was looking at the soft ground seemed was not visible to the TO and as such the front tire sunk in. After the tire went down, me and captain Ernest got down to access the depth to which the tire sunk and proceeded to get the passengers out of the tonner as higher hq personnel (from EUTC and 30SCE) attended to the incident.	STATEM	ENT OF	3SG RAYAPPAN TONY VICTAR						ALIA	SES	-	
DIALECT  NA  LANGUAGE SPOKEN  ENGLISH  TEL NO  86833580  ADDRESS  Bukit Batok East Ave 3, Blk 222, #02-142  INTERPRETED BY  RECORDED BY  2LT LEE AO XUAN  RANK  LIT  TIME  2300  DATE  250423  SIGN  NA  Time: 16.45(25/04/23) I was sitting on the front passenger seat (middle). Travelling along old cck road, me and the other veh comm saw incoming coming on the other lane and it slowed down and stopped for us to go past it, near mirvana memorial garden. Due to the narrowness of the road, TO using his judgment decided to drive slightly off the axis slowly to move forward after the incoming (opposite direction) stopped, as the incoming had no place to veer to the right to go past my tonner. When trying to move forward, there was a unexpected soft ground on the side of the axis, and the front left tire got brought down into the soft ground. The front passenger and myself were managing the route, I was looking out in front for the TO' movement while captain Ernest was looking at the side to guide the TO and told the driver to be careful when trying to move past the incoming, but the soft ground seemed was not visible to the TO and as such the front tire sunk in. After the tire went down, me and captain Ernest got down to access the depth to which the tire sunk and proceeded to get the passengers out of the tonner as higher hq personnel (from EUTC and 30SCE) attended to the incident.	NRIC N	0	TXXXX966Z	1966Z AGE		20		MALE/FEMALE		MALE		
ADDRESS  Bukit Batok East Ave 3, Blk 222, #02-142  INTERPRETED BY  RECORDED BY  2LT LEE AO XUAN  RANK  2LT TIME 2300 DATE 250423 SIGN NA  Time: 16.45(25/04/23) I was sitting on the front passenger seat (middle). Travelling along old cck road, me and the other veh comm saw incoming coming on the other lane and it slowed down and stopped for us to go past it, near nirvana memorial garden. Due to the narrowness of the road, TO using his judgment decided to drive slightly off the axis slowly to move forward after the incoming (opposite direction) stopped, as the incoming had no place to veer to the right to go past my tonner. When trying to move forward, there was a unexpected soft ground on the side of the axis, and the front left tire got brought down into the soft ground. The front passenger and myself were managing the route, I was looking out in front for the TO' movement while captain Ernest was looking at the side to guide the TO and told the driver to be careful when trying to move past the incoming, but the soft ground seemed was not visible to the TO and as such the front tire sunk in. After the tire went down, me and captain Ernest got down to access the depth to which the tire sunk and proceeded to get the passengers out of the tonner as higher hq personnel (from EUTC and 30SCE) attended to the incident.	EMPLO	YMENT	SAF			-			NATIONALITY		SINGAPOREAN	
RECORDED BY  2LT LEE AO XUAN  RANK  2LT  TIME  2300  DATE  250423  SIGN  NA  Time: 16.45(25/04/23) I was sitting on the front passenger seat (middle). Travelling along old cck road, me and the other veh comm saw incoming coming on the other lane and it slowed down and stopped for us to go past it, near nirvana memorial garden. Due to the narrowness of the road, TO using his judgment decided to drive slightly off the axis slowly to move forward after the incoming (opposite direction) stopped, as the incoming had no place to veer to the right to go past my tonner. When trying to move forward, there was a unexpected soft ground on the side of the axis, and the front left tire got brought down into the soft ground. The front passenger and myself were managing the route, I was looking out in front for the TO' movement while captain Ernest was looking at the side to guide the TO and told the driver to be careful when trying to move past the incoming, but the soft ground seemed was not visible to the TO and as such the front tire sunk in. After the tire went down, me and captain Ernest got down to access the depth to which the tire sunk and proceeded to get the passengers out of the tonner as higher hq personnel(from EUTC and 30SCE) attended to the incident.	DIALEC	T	NA			ENGLISH		TEL NO		86833580		
RECORDED BY  2LT LEE AO XUAN  RANK  2LT  TIME  2300  DATE  250423  SIGN  NA  Time: 16.45(25/04/23) I was sitting on the front passenger seat (middle). Travelling along old cck road, me and the other veh comm saw incoming coming on the other lane and it slowed down and stopped for us to go past it, near nirvana memorial garden. Due to the narrowness of the road, TO using his judgment decided to drive slightly off the axis slowly to move forward after the incoming (opposite direction) stopped, as the incoming had no place to veer to the right to go past my tonner. When trying to move forward, there was a unexpected soft ground on the side of the axis, and the front left tire got brought down into the soft ground. The front passenger and myself were managing the route, I was looking out in front for the TO' movement while captain Emest was looking at the side to guide the TO and told the driver to be careful when trying to move past the incoming, but the soft ground seemed was not visible to the TO and as such the front tire sunk in. After the tire went down, me and captain Emest got down to access the depth to which the tire sunk and proceeded to get the passengers out of the tonner as higher hq personnel(from EUTC and 30SCE) attended to the incident.	ADDRE	SS	Bukit Batok East I	Ave 3, Blk 2	222, #02-1	42						
Time: 16.45(25/04/23) I was sitting on the front passenger seat (middle). Travelling along old cck road, me and the other veh comm saw incoming coming on the other lane and it slowed down and stopped for us to go past it, near nirvana memorial garden. Due to the narrowness of the road, TO using his judgment decided to drive slightly off the axis slowly to move forward after the incoming (opposite direction) stopped, as the incoming had no place to veer to the right to go past my tonner. When trying to move forward, there was a unexpected soft ground on the side of the axis, and the front left tire got brought down into the soft ground. The front passenger and myself were managing the route, I was looking out in front for the TO' movement while captain Emest was looking at the side to guide the TO and told the driver to be careful when trying to move past the incoming, but the soft ground seemed was not visible to the TO and as such the front tire sunk in. After the tire went down, me and captain Emest got down to access the depth to which the tire sunk and proceeded to get the passengers out of the tonner as higher hq personnel (from EUTC and 30SCE) attended to the incident.	INTERP	RETED BY										
the other veh comm saw incoming coming on the other lane and it slowed down and stopped for us to go past it, near nirvana memorial garden. Due to the narrowness of the road, TO using his judgment decided to drive slightly off the axis slowly to move forward after the incoming (opposite direction) stopped, as the incoming had no place to veer to the right to go past my tonner. When trying to move forward, there was a unexpected soft ground on the side of the axis, and the front left tire got brought down into the soft ground. The front passenger and myself were managing the route, I was looking out in front for the TO' movement while captain Emest was looking at the side to guide the TO and told the driver to be careful when trying to move past the incoming, but the soft ground seemed was not visible to the TO and as such the front tire sunk in. After the tire went down, me and captain Emest got down to access the depth to which the tire sunk and proceeded to get the passengers out of the tonner as higher hq personnel(from EUTC and 30SCE) attended to the incident.	RECOR	DED BY		RANK	2LT	TIME	2300	DATE		250423	SIGN	NA
DATE 250423 SIGNATURE OF SENT VIA TEXT>	the other it, near slightly had no soft gro passeng Ernest incomin tire wer the pass	er veh comm nirvana men off the axis place to veen ound on the ger and myse was looking ng, but the nt down, me as sengers out o	23) I was sitting on the front passenger seat (middle). Travelling along old cck road, me and is saw incoming coming on the other lane and it slowed down and stopped for us to go parmorial garden. Due to the narrowness of the road, TO using his judgment decided to drive slowly to move forward after the incoming (opposite direction) stopped, as the incoming to to the right to go past my tonner. When trying to move forward, there was a unexpected side of the axis, and the front left tire got brought down into the soft ground. The frontleft were managing the route, I was looking out in front for the TO' movement while captain at the side to guide the TO and told the driver to be careful when trying to move past the soft ground seemed was not visible to the TO and as such the front tire sunk in. After the and captain Ernest got down to access the depth to which the tire sunk and proceeded to go of the tonner as higher higher sonnel (from EUTC and 30SCE) attended to the incident.					o go past to drive acoming expected he front captain past the After the ed to get				

Figure C-2: Statement of VC



Fig D-1: Police Report Part 1

Date/Time: 31/05/2023 15:38

Classification Of Case:

Signature Of Interpreter: Not applicable

Officer In-Charge Of Case:





2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. J/20230531/7054

road, i saw a truck slowing down and giving way to me so i proceed forward slowly. After that i saw my tonner and the truck was pretty close to me so i check on my left is it clear to move to the grass patch. When i moved slightly a bit to the left, the grass patch soil gave way and the tonner hit the railing after that i pull to a stop and engage handbrake.

Subjects Involved							
Victim							
Person Name	AMIRUL HAQIM BIN RAHMAD						
ID Type	NRIC NO	ID No	T 920J				
Gender	Male	Age	21				
Race	Javanese	Language	English				
Occupation	National Service Full Time	Address					
Mobile No		Is Informant A Victim?	Yes				
Person Name	AMIRUL HAQIM BIN RAHMAD (Informant)						
	·						

Signature Of Officer Recording The Report:	Signature Of Informant:
Not applicable	The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 31/05/2023 15:38
Officer In-Charge Of Case:	Classification Of Case:

Fig D-2: Police Report Part 2