

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01 (Claims & Performance Management)
Singapore 068897

Our File No: CC3/AIS23006301/RQP3E2**Date:** 02/08/2023**REFERENCE**

Insured/Claimant: ANNIE JOAN CHOONG TUCK CHING Policy No: SP2004844242
Date of Loss: 19/06/2023 Nature of Claim: OD Claim No: 202332009695

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMS9897R**
Make & Model: VOLKSWAGEN BEETLE CABRIOLET, 1.2 TSI Engine No: CYV643099
DSG (A)
Reg. Date: 25/02/2020 (Man. Year: 2019) Chassis No: WVVZZZ16ZKM508092
Colour: Orange Odometer: 31780 km
Engine Capacity: 1197 cc
Market Value/New Car Price: S\$133,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/45Z R18 Rear Tyre Size: 235/45Z R18
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,096.36	1,983.40	1,112.96	35.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,930.00	1,750.00	2,180.00	55.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,026.36	3,733.40	3,292.96	46.87
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	6,426.36	3,133.40	3,292.96	51.24
+ GST 8.00/8.00% (S\$)	514.11	250.67	263.44	51.24
Nett Amount (S\$)	6,940.47	3,384.07	3,556.40	51.24

INSPECTION

Date of Assignment: 21/06/2023
Date Inspected: 23/06/2023 Inspected At: Volkswagen Group Singapore Pte Ltd
247 ALEXANDRA ROAD
Singapore 159934
Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 27 Jul 2023)	
Parts:	N/A	VOLKSWAGEN BEETLE CABRIOLET 1.2 TSI DSG (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMS9897R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*COVER FOR BUMPER PRIMED	Deformed	1,150.40 FS	*1,150.40 FS
2	1	*HOLDER FOR COVER BUMPER BUMPER UPPER HOLDER LH	Cracked	42.32 FS	*42.32 FS
3	1	*HOLDER FOR COVER BUMPER BUMPER UPPER HOLDER RH	Not Necessary	42.32 FS	*- FS
4	1	*GUIDE PIECE BUMPER SIDE BRACKET LH	Not Necessary	43.23 FS	*- FS
5	1	*GUIDE PIECE BUMPER SIDE BRACKET RH	Not Necessary	43.23 FS	*- FS
6	4	*RIVET	Not Necessary	2.59 FS	*- FS
7	1	*BUMPER BRACKET REINFORCEMENT	Bent	502.26 FS	*502.26 FS
8	1	*FOAM INSERT BUMPER FOAM LH (SIDE)	Not Necessary	159.82 FS	*- FS
9	1	*FOAM INSERT BUMPER FOAM RH (SIDE)	Not Necessary	159.82 FS	*- FS
10	1	*FOAM INSERT BUMPER FOAM LH (UPPER)	Not Necessary	34.62 FS	*- FS
11	1	*FOAM INSERT BUMPER FOAM RH (UPPER)	Not Necessary	34.62 FS	*- FS
12	1	*GRILLE SATIN BLACK / BRIGHT BUMPER CTR LOWER GRILLE	Not Necessary	358.55 FS	*- FS
13	1	*GRILLE BLACK / SATIN BLACK / LHS FOG LAMP GRILLE	Deformed	208.42 FS	*208.42 FS
14	1	*GRILLE BLACK / SATIN BLACK / RHS FOG LAMP GRILLE	Not Necessary	202.49 FS	*- FS
15	2	*FLAT CONTACT HOUSING WITH H/LAMP WIRE HOUSING	Not Necessary	31.67 FS	*- FS
16	1	*FRONT NUMBER PLATE	Bent	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)

3,096.36

1,983.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR	New	200.00	200.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	360.00	360.00
3	TO ALIGN HEADLIGHT	New	100.00	100.00
4	LABOUR	New	1,680.00	560.00
5	SPRAY PAINT	New	1,590.00	530.00
Gross Labour Cost (S\$)			3,930.00	1,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >