

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/HLA23006312/UVP3E2**Date:** 12/07/2023REFERENCE

Handling Insurer:	HL Assurance Pte Ltd	Policy No:	MP317635
Claimant Vehicle No :	SLT6698A	Insured Vehicle No :	SLZ1112A
Date of Loss:	20/06/2023	Nature of Claim:	TP
		Claim No:	MPC04321

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT6698A	Engine No:	CVN045375
Make & Model:	AUDI A4, 1.4 (A)	Chassis No:	WAUZZZF43JA023521
Reg. Date:	06/11/2017 (Man. Year: 2017)	Odometer:	42995 km
Colour:	Black		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,433.01	3,779.06	2,653.95	41.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,480.00	1,200.00	1,280.00	51.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,913.01	4,979.06	3,933.95	44.14
Approved Total (Overridden) (S\$)		3,900.00		
(S\$)	8,913.01	3,900.00	5,013.01	56.24
+ GST 8.00/8.00% (S\$)	713.04	312.00	401.04	56.24
Nett Amount (S\$)	9,626.05	4,212.00	5,414.05	56.24

INSPECTION

Date of Assignment:	21/06/2023	
Date Inspected:	04/07/2023	Inspected At:
Estimated Period of Repair:	4.0 days	Bluwel Automotive Service PL Blk 1 Kaki Bukit Ave 6 #01-28/53/55/56 (Main Office) Singapore 417883

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jul 2023)
Parts:	143	AUDI A4 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT6698A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed / Torn	1,998.22 FL	*1,998.22 FL
2	1		*REAR BUMPER LOWER	Deformed	295.00 FL	*295.00 FL
3	1		*REAR BUMPER REFLECTOR N/S	Not Necessary	42.00 FL	*- FL
4	2		*REAR BUMPER PDC SENSORS	Malfunction	490.00 FL	*490.00 FL
5	4		*REAR BUMPER PDC SENSOR BRACKETS	Necessary	180.00 FL	*180.00 FL
6	2		*REAR BUMPER SIDE HOLDERS	Not Necessary	180.00 FL	*- FL
7	1		*REAR BUMPER BEAM	Bent	796.00 FL	*796.00 FL
8	1		*REAR BUMPER LOWER BRACKET N/S	Not Necessary	86.00 FL	*- FL
9	1		*REAR BUMPER INNER RETAINER	Cracked	166.11 FL	*166.11 FL
10	1		*REAR END PANEL OUTER	Repair	902.00 FL	*- FL
11	1		*REAR END PANEL INNER	Repair	449.00 FL	*- FL
12	1		*REAR END PANEL TOP GARNISH	Serviceable	260.00 FL	*- FL
13	1		*TAILLAMP N/S	Not Necessary	822.00 FL	*- FL
14	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
15	1		*REAR END PANEL SEALANT	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,766.33	3,975.33
- List Item Discount on L Items 5.00/5.00% (\$\$)	333.32	196.27
Total Parts (\$\$)	6,433.01	3,779.06

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REAR PDC SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR CUSHION UPHOLSTERY	New	120.00	80.00
4	TO DIAGNOSTIC & REPROGRAMME SYSTEM	New	180.00	50.00
5	TO SPRAY RUST PROOFING	New	150.00	0.00
6	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,000.00	500.00
7	TO PUTTY & SPRAY PAINTING	New	900.00	500.00
Gross Labour Cost (\$\$)			2,480.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >