



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 6317E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	DEFORMED	481.10	481.10
1	FRONT BUMPER MOULDING CENTRE	CUT	368.50	368.50
1	FRONT BUMPER GRILLE LH	CUT	186.90	186.90
1	FRONT DAY RUNNING LIGHT LH	NOT NECESSARY	642.50	-
1	FRONT BUMPER BRACKET LH	NOT NECESSARY	41.40	-
1	HEADLAMP LH	CUT	2,110.30	2,110.30
1	HEADLAMP SUPPORT PANEL	NOT NECESSARY	949.30	-
1	FRONT FENDER LH	BENT	588.80	588.80
1	FRONT FENDER SHIELD LH	NOT NECESSARY	164.70	-
1	FRONT FENDER EMBLEM RH	NECESSARY	28.80	28.80
1	FRONT WHEEL CAP LH	CUT	346.40	346.40
10	FRONT BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
	LESS 20% DISCOUNT		-1,186.14	-826.56
			4,744.56	3,306.24
	<b><u>LABOUR</u></b>			
	PANEL BEATING.		700.00	350.00
	SPRAY PAINT.		600.00	500.00
	RESET FRONT WHEEL ALIGNMENT.		60.00	60.00
	CHECK LIGHTING.		60.00	30.00
			1,420.00	940.00
	<b>GRAND TOTAL</b>		<b>6,164.56</b>	<b>4,246.24</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>3,400.00</b>

Report Ref No. NS/INC23006322/Tqp3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.