

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.
TEL: 6456 9830 • FAX: 6458 0128
Business Regn No: 269436/00J

16 JUNE 2023

India International Insurance PL
64, Cecil Street
#04/#05/#06-02 10B Building
Singapore 049711

Not Authorised
1/1 Day @
Repair After Paint
3 days

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle no: SLK3123J
Accident involving vehicle no: SGZ7538A/SLK3123J
DOA: 15/06/2023 at Clementi Rd, Singapore

Dear officer in charge
Estimate cost of repair for vehicle no: SGZ7538A
To supplied:

Description	Qty	Amount
Front bumper	<i>Bul/R</i> 1	458.00
Front bumper retainer RH	1	<i>0.7</i> 82.30
Front fender RH	<i>R</i> 1	761.45
Front fender - vvti emblem	<i>in</i> 1	43.50
Front fender cowlings	<i>in</i> 1	163.40
Headlamp	1	2,804.10
Foglamp	<i>in</i> 1	256.90
Foglamp cover	<i>in</i> 1	112.90
Tire	<i>in</i> 1	120.00
Rim (In set)	<i>in</i> 1	340.00
Cowling clip	<i>in</i>	38.00
Bumper clip	<i>in</i>	35.00
Parts		
Parts less 25%		5,215.55
		3,911.66

1. Wheel alignment
2. Remove damaged parts & attachments
Cut/weld damaged panel
Repair dented area
Replace/realign all parts into same position
3. To spray paint

nn 100.00 X

800.00 *400d*
850.00 *400d*

5,661.66

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: