



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 1164K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT HEADLAMP	MTG CRACKED	2,590.70	2,590.70
1	FRONT BONNET	BENT	1,155.40	1,155.40
1	FRONT BUMPER RETAINER	DISTORTED	25.30	25.30
	LESS 10% DISCOUNT		-377.14	-
	LESS 20% DISCOUNT		-	-754.28
			3,394.26	3,017.12
	<u>LABOUR</u>			
	SPRAY PAINTING IN FENDER AND BONNET.		350.00	250.00
	TO REPLACE ABOVE PARTS.		400.00	220.00
			750.00	470.00
	GRAND TOTAL		4,144.26	3,487.12
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)			3,487.12

Report Ref No. CS/LPC23006337/Kqp3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.