

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01 (Claims & Performance Management)
Singapore 068897

Our File No: CC3/AIS23006342/RVP3Q2**Date:** 19/07/2023**REFERENCE**

Insured/Claimant:	WU CHENGHAK	Policy No:	AIS/2023/0000406/000033	
Date of Loss:	16/06/2023	Nature of Claim:	OD	Claim No: 202332009812

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMZ8090X		Engine No:	CZP243210
Make & Model:	VOLKSWAGEN PASSAT, 2.0 (A)		Chassis No:	WVWZZZ3CZME032479
Reg. Date:	20/05/2021 (Man. Year: 2020)		Odometer:	20962 km
Colour:	Grey			
Engine Capacity:	1984 cc			
Market Value/New Car Price:	S\$169,000.00			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45 R18	Rear Tyre Size:	235/45 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,498.92	6,866.41	632.51	8.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,460.00	2,840.00	1,620.00	36.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,958.92	9,706.41	2,252.51	18.84
- Excess (\$\$)	600.00	600.00	0.00	0.00
(\$\$)	11,358.92	9,106.41	2,252.51	19.83
+ GST 8.00/8.00% (\$\$)	908.71	728.51	180.20	19.83
Nett Amount (\$\$)	12,267.63	9,834.92	2,432.71	19.83

INSPECTION

Date of Assignment:	22/06/2023		
Date Inspected:	26/06/2023	Inspected At:	Volkswagen Group Singapore Pte Ltd 247 ALEXANDRA ROAD Singapore 159934
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Jul 2023)
Parts:	143	VOLKSWAGEN PASSAT 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMZ8090X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HOOD FRT BONNET	Bent	1,308.25 FS	*1,308.25 FS
2	1		*FLAP HINGE LH	Not Necessary	103.41 FS	*- FS
3	1		*FLAP HINGE RH	Not Necessary	103.41 FS	*- FS
4	1		*LOCKING CATCH BONNET LATCH	Not Necessary	72.53 FS	*- FS
5	1		*COVER FOR BUMPER PRIMED	Deformed	1,360.00 FS	*1,360.00 FS
6	1		*SET SENSOR BRACKETS	Necessary	38.40 FS	*38.40 FS
7	1		*GUIDE PIECE RHS BUMPER INNER BRACKET	Not Necessary	48.62 FS	*- FS
8	1		*GUIDE PIECE RHS BUMPER SIDE BRACKET	Not Necessary	48.62 FS	*- FS
9	1		*GUIDE PIECE BUMPER CTR BRACKET	Not Necessary	97.36 FS	*- FS
10	1		*FOAM INSERT	Not Necessary	102.33 FS	*- FS
11	1		*RADIATOR GRILLE SATIN BLA	Cut	495.16 FS	*495.16 FS
12	1		*COOLING AIR GRILLE SATIN B RHS FOG LAMP GRILLE	Cracked	97.49 FS	*97.49 FS
13	1		*LED HEADLIGHT WITH MATRIX RHS H/LAMP	Cracked	3,236.32 FS	*3,236.32 FS
14	1		*TRIM COVER RHS H/LAMP TOP CHROM	Cracked	31.79 FS	*31.79 FS
15	1		*TRIM COVER RHS H/LAMP LOWER CHROM	Not Necessary	56.23 FS	*- FS
16	1		*GASKET	Necessary	9.69 FS	*9.69 FS
17	1		*HALOGEN FOG LIGHTS WITH S RHS FOG LAMP	Cracked	289.31 FS	*289.31 FS
Total Parts (S\$)					7,498.92	6,866.41

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	B&P CHECK SHORT CIRCUIT /HARNESS REPAIR	New	200.00	200.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	360.00	360.00
3	TO ALIGN LED HEADLIGHT	New	100.00	100.00
4	LABOUR	New	1,680.00	1,120.00
5	SPRAY PAINT	New	2,120.00	1,060.00
Gross Labour Cost (S\$)			4,460.00	2,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >