

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 1922C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER FASCIA	BUCKLED	2,076.00	2,076.00
1	REAR BUMPER LOWER CHROME	SCRATCHED	384.00	384.00
1	REAR BUMPER LOWER GARNISH	SERVICEABLE	372.00	-
2	REAR O/S BUMPER PARKING SENSOR @ S\$198.00	MISSING (1PIECE ONLY)	396.00	198.00
2	RR O/S PARKING SENSOR O RING @ S\$12.00	NECESSARY	24.00	24.00
1	REAR O/S BUMPER SIDE RETAINER	CRACKED	111.00	111.00
1	REAR O/S BUMPER REFLECTOR	SERVICEABLE	63.00	-
1	O/S TAILLAMP	BROKEN	898.00	855.00
1	REAR O/S FENDER	BENT	2,320.00	2,320.00
	LESS 10% DISCOUNT		-664.40	-596.80
			5,979.60	5,371.20
	SPECIAL NETT ITEMS			
1	REAR W/S GLASS SEALANT (SN)	NECESSARY	60.00	40.00
1	SET REAR BUMPER RIVET (SN)	NECESSARY	30.00	30.00
			90.00	70.00
	<u>LABOUR</u>			
	TO REMOVE & REFIX REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.		150.00	120.00
	TO REMOVE ROOF LINING, FRONT AND REAR SEATS, TRIM BOARD AND CARPET.		180.00	120.00
	TO APPLY UNDERSEALING.		80.00	30.00
	TO PUTTY AND SPRAY REPLACED PARTS.		800.00	700.00
	TO REMOVE, CUT-OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ABOVE PARTS.		1,000.00	600.00
			2,210.00	1,570.00
	GRAND TOTAL		8,279.60	7,011.20

Report Ref No. CS/FCI23006374/Kny3m4



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		5,600.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/FCI23006374/Kny3m4

**KONG SENG CHEONG** 

**Licensed Appraiser**