

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	GREAT AMERICAN	N INSURANCE COMPANY		Ref:	CS3/GAI23006375/Tqy3e2	
	3 TEMASEK AVEN TOWER SINGAPO		Date:	04/07/2023		
				Code:	GAI	
1.	1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SKR 8455T	Veh. Inspected	t	SMH 1897B	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CLMOMVP000001347	Excess (\$)		0.00	
	Assign From	ELIZABETH CHEW	Assign Date		23/06/2023	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA FREED	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	GB71077064	Colour		GREEN	
	Odometer	133029 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	185/60 R15	WINDFORCE		6 mm	
	L/H Front Tyre	185/60 R15	WINDFORCE		6 mm	
	R/H Rear Tyre	185/60 R15	WINDFORCE		6 mm	
	L/H Rear Tyre	185/60 R15	WINDFORCE		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
5.	5. General Information					
	Accident Date	16/06/2023	Inspect Date /	Time	27/06/2023 (12:00 PM)	
	Survey held at	AII AUTO				
	23 KAKI BUKIT AVENUE 4 KAKI BUKIT VICOM #04-01 SINGAPORE 415933					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,500-\$7,500					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days					

Report Ref No. CS3/GAI23006375/Tqy3e2

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor