



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 236K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	LH SLIDING DOOR	BENT	3,300.00	1,850.00
1	LH SLIDING DOOR GARNISH	BENT	365.00	195.00
1	LH SLIDING DOOR LOCK	TO REPAIR SEE LABOUR	797.00	-
1	LH SLIDING DOOR HANDLE	SERVICEABLE	274.00	-
1	LH SLIDING GLASS MOULDING	SERVICEABLE	60.00	-
1	REAR LH FENDER	TO REPAIR SEE LABOUR	3,159.00	-
1	REAR LH FENDER GARNISH	CUT	452.00	180.00
1	REAR BUMPER	CUT	1,119.00	750.00
1	REAR LH WHEEL RIM CAP	DENTED / CUT	130.00	130.00
	LESS 10% DISCOUNT		-965.60	-310.50
			8,690.40	2,794.50
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
			50.00	50.00
	<u>LABOUR</u>			
	TO KNOCK & STRAIGHTEN ON ACCIDENT AREA, TO REMOVE & REFIT REAR LH DAMAGE PARTS. INCLUSIVE OF THE REPAIR OF LH SLIDING DOOR LOCK AND REAR LH FENDER.		1,000.00	600.00
	TO PUTTY & RESPRAY ON REAR LH DAMAGE AREA.		800.00	600.00
	TO CHECK WIRING & INSTALL REVERSE SENSOR.		50.00	50.00
			1,850.00	1,250.00
	GRAND TOTAL		10,590.40	4,094.50
	RECOMMENDED COST OF REPAIRS			4,094.50

Report Ref No. CS/CTI23006378/Kqp3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.