

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/III23003039/DVY3E2-1**Date:** 03/07/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_02
Claimant Vehicle No : SJR2629K **Insured Vehicle No :** SLK3765G
 Date of Loss: 19/03/2023 Nature of Claim: TP Claim No: MFL2023D0003159

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJR2629K**
 Make & Model: MERCEDES-BENZ C180K, 1.6 (A) Engine No: 27191031344410
 Reg. Date: 25/04/2011 (Man. Year: 2011) Chassis No: WDD2040452A525756
 Colour: Yellow Odometer: 164394 km
 Engine Capacity: 1597 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
 Front Left Side: Habilead 6 mm Rear Left Side: Habilead 6 mm
 Front Right Side: Habilead 6 mm Rear Right Side: Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,664.93	2,899.30	4,765.63	62.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,900.00	1,220.00	2,680.00	68.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,564.93	4,119.30	7,445.63	64.38
Approved Total (Overridden) (S\$)		3,300.00		
(S\$)	11,564.93	3,300.00	8,264.93	71.47
+ GST 8.00/8.00% (S\$)	925.19	264.00	661.19	71.47
Nett Amount (S\$)	12,490.12	3,564.00	8,926.12	71.47

INSPECTION

Date of Assignment: 23/06/2023

Date Inspected: 27/03/2023 Inspected At:

Estimated Period of Repair: 4.0 days

Chip Soon Auto Supply Co Pte Ltd (HQ)
 BLOCK 9002 #01-74 TAMPINES STREET 93,
 TAMPINES INDUSTRIAL PARK A
 Singapore 528836

Adjuster: BRYAN TANI**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Jul 2023)
Parts:	143	MERCEDES-BENZ C180K 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJR2629K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut / Cracked	1,280.74 FL	*1,280.74 FL
2	2		*REAR BUMPER SIDE BRACKET	Not Necessary	151.20 FL	*- FL
3	2		*REAR BUMPER SIDE RETAINER	Necessary	97.00 FL	*97.00 FL
4	1		*REAR BUMPER CENTRE DIFFUSER (ACCESSORIES-CARBON)	Cut / Distorted	1,100.00 FS	*600.00 FS
5	1		*REAR BUMPER REINFORCEMENT	Bent	795.57 FL	*624.00 FL
6	1		*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
7	1		*REAR BOOTLID PANEL	Repair	1,796.80 FL	*- FL
8	1		*REAR BOOTLID LOGO	Necessary	75.80 FL	*75.80 FL
9	1		*REAR BOOTLID INNER TRIM GARNISH CLIPS	Not Necessary	80.00 FS	*- FS
10	1		*REAR BOOTLID LOCK ASSY	Not Necessary	260.80 FL	*- FL
11	1		*REAR END PANEL	Repair	1,017.20 FL	*- FL
12	1		*REAR END PANEL TOP GARNISH	Not Necessary	292.40 FL	*- FL
13	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	80.00 FS	*- FS
14	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
15	1		*REVERSE SENSOR (4PCS)	Cut / Malfunction(2Pcs Only)	790.00 FL	*395.00 FL
16	1		*SET REVERSE SENSOR MOUNT	Necessary	48.90 FL	*48.90 FL
17	1		*REAR BOOTLID WEATHER STRIP	Not Necessary	332.40 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,358.81	3,151.44
- List Item Discount on L Items 10.00/10.00% (\$\$)	693.88	252.14
Total Parts (\$\$)	7,664.93	2,899.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE / RENEW THE REAR ACCIDENT DAMAGED PORTION. TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS. (\$350.00 PER DAY)	New	1,400.00	450.00
2	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS INCLUDING TO RE-SET	New	80.00	60.00
3	TO MEASURE, DRILL HOLES ON REPLACED FRONT BUMPER, POSITION AND INSTALL REVERSE SENSOR, CHECK AND TEST ON THE DISTANCE AND FUNCTIONS	New	120.00	50.00
4	TO SUPPLY RUST PROOFING ON AFFECTED PANELS	New	100.00	30.00
5	TO CONDUCT STAR - DIAGNOSTIC TO RESET AND CALIBRATE REVERSE SENSOR	New	450.00	30.00
6	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY REAR BUMPER, BOOTLID, END PANEL AND ETC... (\$350.00 PER PANEL)	New	1,750.00	600.00
Gross Labour Cost (\$\$)			3,900.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >