

Motor Vehicle Appraiser and Insurance Loss Adjuster Reliance Appraisal Pte Ltd© 272D, Sengkang Central Singapore 544272 Co. Reg. No. 202214158E Email: info@ra-appraisal.com Tel: (65) 9010 7765

# **INVOICE**

To:

Chip Soon Auto Supply Co Pte Ltd

Invoice No.:

202303012

Attn:

Blk 9002 Tampines Street 93 #01-74 Tampines

10/5/2023

Date:

Industrial Park A Singapore 528836

020 CODO 20 GEORGE 1793 EC	
Service rendered for appraisal	/ inspection report: SJR2629K

Professional inspection fees

Photographs

45 pcs

SGD 430.00 SGD 45.00

AMOUNT

Transport fees

Re-inspection fees (work in progress, post repair inspection)

DESCRIPTION

SGD 60.00 SGD 80.00

Total Singapore Dollars Six Hundred Fifteen Only

SGD 615.00

Registration no.: SJR2629K

Make/Model:

MERCEDES BENZ C180K

Our reference:

202303012

All payments made payee to:-Reliance Appraisal Pte Ltd

for Reliance Appraisal Pte Ltd



Reliance Appraisal Pte Ltd© 272D, Sengkang Central Singapore 544272 Co. Reg. No. 202214158E Email: info@ra-appraisal.com Tel: (65) 9010 7765

### VEHICLE DAMAGE ASSESSMENT REPORT

Attn: Chip Soon Auto Supply Co Pte Ltd Adjuster Ref: 202303012 Blk 9002 Tampines Street 93 #01-74 Tampines Industrial Park A 10/5/2023 Date: TP

Singapore 528836 Type of Claim:

CLAIM DETAILS

Claim No: Handling Repairer: Chip Soon Auto Supply Co Pte Ltd

Claimant Vehicle No: SJR2629K Insured Vehicle No: SLK3765G

Claimant: LIM HOE SING Date of Loss: 19/3/2023 Policy No: NA

VEHICLE DETAILS

Vehicle No: SJR2629K Colour: Blue

Model: C180K Make: MERCEDES BENZ Registration Date: 25/04/2011 (Man. Year: 2011) Engine No: 27191031344410

COE Category: A - Car (1600cc & below) WDD2040452A525756 Chassis No:

Engine Capacity: Market Value/ 1597 New Car Price (S\$):

Sum Insured (S\$): Market Value/New Car Price Odometer (km): 164,394

CONDITION OF VEHICLE DURING INSPECTION

General Condition: Fair Steering: In Order Footbrake: In Order Pre-accident Condition: Good Engine Modification: No Handbrake: In Order

CONDITION OF TYRES

HEADKING Rear Tyre Brand: HEADKING Front Tyre Brand:

Front Left Side: 225/45ZR17 6mm Rear Left Side: 225/45ZR17 6mm Front Right Side: 225/45ZR17 6mm Rear Right Side: 225/45ZR17 6mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer	Adjuster	Difference	Diff%
Part(s)	7,664.93	5,756.07	1,908.86	24.90
Labour	2,150.00	1,740.00	410.00	19.07
Paintwork Labour	1,750.00	1,400.00	350.00	20.00
Gross Total (S\$)	11,564.93	8,896.07	2,668.86	23.08
(Lump Sum) Adjusted Total (S\$)		7,150.00	4,414.93	38.18
- Excess (S\$)	NA	NA	0.00	0.00
Sub Total (S\$)	11,564.93	7,150.00	4,414.93	38.18
+ 8% GST (S\$)	NA	NA	NA	NA
Nett Repair Cost + 8% GST (S\$)	11,564.93	7,150.00	4,414.93	38.18
Nett Liability (S\$)	11,564.93	7,150.00	4,414.93	38.18

**INSPECTION DETAILS** 

Date of Assignment: 27/3/2023 Inspected At: Chip Soon Auto Supply Co Pte Ltd Date Inspected: 27/3/2023 Blk 9002 Tampines Street 93 #01-74 Estimated Repair Period: 5.0 day(s) Tampines Industrial Park A Singapore Surveyed on a "without prejudice" basis 528836

Adjuster: Ho Too Boon

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### Confidential



Reliance Appraisal Pte Ltd© 272D, Sengkang Central Singapore 544272 Co. Reg. No. 202214158E Email: info@ra-appraisal.com Tel: (65) 9010 7765

Adjuster Ref: 202303012

WITHOUT PREJUDICE

Dear Sir,

Re: Third Party Claim For Vehicle Registration No.

SJR2629K

We refer to your instruction to appraise the above-mentioned vehicle on 27/03/2023 Which was involved in an accident that happen on the 19/03/2023@2305hrs at Simei Slip Road towards PIE.

A static inspection was carried out and our report is enclosed for your perusal. The estimated cost of repair submitted by Messrs. Chlp Soon Auto Supply Co Pte Ltd for SGD 11564.93 as per our attached schedule has been inspected thoroughly by us against the actual damages sustained on the above-mentioned vehicle and we recommend the replacement and rectification accordingly.

Our revised quotation for the repair is SGD 8896.07. In our opinion, it to be excessive. Therefore, we recommend a contract lump-sum repair cost. This is more economical than to have the above-mentioned vehicle repaired on parts by/for parts basis. Invariably, the repairer has the prerogative/option for the recommended replacement parts to either be repaired or be replaced.

We have negotiated with the repairer and they have agreed to repair the above-mentioned vehicle for SGD 7150 NETT. Which, in our opinion is fair and reasonable.

The repairer has agreed to undertake the repairs to your requirement at the recommended contract lump-sum. However, we have not given any instruction and authorisation to the repairer to proceed with the repairs.

Under normal circumstances, the entire repair of the damaged vehicle should be completed within a reasonable period of 5 days.

In accordance, we have **Not Authorised** the repair to the damaged vehicle and the survey was conducted strictly on a "WITHOUT PREJUDICE" basis.

We are reverting the matter to you for a decision, and enclosed is our vehicle inspection report, appraisement schedule and invoice for services rendered.

Please do not hesitate to contact us if you have any queries on this matter.

Yours faithfully, Reliance Appraisal Pte Ltd© RA

Ho Too Boon Motor Vehicle Appraiser Encls. :

The information contained in these document may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you received this document by error, please contact us immediately to arrange for its return.

## Recommended Part(s)

No	Qty	art N	Description	Condition	Repairer		Adjuster	
1	1		Rear bumper	Cut/Cracked	1,280.74	L	1,280.74	L
2	1		Rear bumper side bracket @ SGD 75.60	Necessary	151.20	L	151.20	L
3	1		Rear bumper side retainer @ SGD 48.50	Necessary	97.00	L	97.00	L
4	1		Rear bumper centre diffuser (accessories-carbon)	Cut/Distorted	1,100.00	S	1,100.00	S
5	1		Rear bumper reinforcement	Bent	795.57	L	795.57	L
6	1		Rear bumper clips	Necessary	80.00	S	60.00	S
7	1		Rear bootlid panel	Bent	1,796.80	L	1,796.80	L
8	1		Rear bootlid logo	Necessary	75.80	L	75.80	L
9	1		Rear bootlid inner trim garnish clips	Necessary	80.00	S	60.00	S
10	1		Rear bootlid weather strip	Necessary	332.40	L	332.40	L
11	1		Rear bootlid lock assy	Not Necessary	260.80	L	0.00	L
12	1		Rear end panel	Repair	1,017.20	Ĺ	0.00	L
13	1		Rear end panel top garnish	Not Necessary	292.40	L	0.00	L
14	1		Rear end panel top garnish clips	Necessary	80.00	S	60.00	S
15	1		Rear end panel sealant	Not Necessary	80.00	S	0.00	S
16	4		Reverse sensor @ SGD 197.50	Cut/Malfunction	790.00	L	395.00	L
17	1		Reverse sensor mount (set)	Necessary	48.90	L	48.90	L
=Lis	t Iter	n. N	=Nett Item, S=Special Nett Item.	Sub Total (SS)	8.358.81		6.253.41	



Necessary	48.90	L	48.90	L
Sub Total (S\$)	8,358.81		6,253.41	
- List Item Discount (S\$)	693.88	10%	497.34	10%
- Nett Item Discount (S\$)	0.00	0%	0.00	0%
+ F Item Margin (S\$)	0.00	0%	0.00	0%
Part(s) Total (S\$)	7,664.93		5,756.07	
- Betterment (S\$)	0.00	0%	0.00	0%
Part(s) Total after Betterment (S\$)	7,664.93		5,756.07	

Recommended	Lahour

No	Description	Repairer	Adjuster
1	To dismantle / renew the <u>Rear</u> accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$350.00 per day)	1,400.00	1,050.00
2	To disconnect front wire harness of electrical component to facilitate repairs, reconnect and check functions including to re-set	80.00	60.00
3	To measure, drill holes on replaced front bumper, position and install reverse sensor, check and test on the distance and functions.	120.00	80.00
4	To supply rust proofing on affected panels	100.00	100.00
5	To conduct STAR - diagnostic to re-set and calibrate reverse sensor	450.00	450.00
6	Supply spray paint material and necessary items to respray rear bumper, bootlid, end panel and etc (\$350.00 per panel)	1,750.00	1,400.00
	Labour Total (S\$)	3,900.00	3,140.00

Confidential

Repairer	Adjuster
7,664.93	5,756.07
2,150.00	1,740.00
1,750.00	1,400.00
11,564.93	8,896.07
	7,150.00
NA	NA
11,564.93	7,150.00
NA	NA
11,564.93	7,150.00
	7,664.93 2,150.00 1,750.00 <b>11,564.93</b> NA 11,564.93 NA

<END OF ESTIMATE>

# RELIANCE APPRAISAL Pte Ltd

Proper

Precise

Profesional




Photo 1



Photo 2

 Proper
 Precise
 Profesional

 Motor Vehicle Appraiser and Insurance Loss Adjuster



Photo 3



Photo 4

Proper Precise Profesional

Motor Vehicle Appraiser and Insurance Loss Adjuster



Photo 5



Photo 6

Precise

Proper Precise Profesional
Motor Vehicle Appraiser and Insurance Loss Adjuster Profesional



Photo 7



Photo 8

 
 Proper
 Precise
 Profesional

 Motor Vehicle Appraiser and Insurance Loss Adjuster
 Our Ref: 202303012



Photo 9



Photo 10

Precise Profesional



Photo 11



Photo 12

 
 Proper
 Precise
 Profesional

 Motor Vehicle Appraiser and Insurance Loss Adjuster
 Our Ref: 202303012



Photo 13




Photo 14

 
 Proper
 Precise
 Profesional

 Motor Vehicle Appraiser and Insurance Loss Adjuster
 Our Ref: 202303012



Photo 15



Photo 16



Precise Profesional

Motor Vehicle Appraiser and Insurance Loss Adjuster



Photo 17



Photo 18



Precise

Profesional



Photo 20



Photo 21



Precise

Profesional



Photo 22



Photo 23



Precise

Profesional



Photo 24



Photo 25

Precise

Profesional



Photo 26



Photo 27



Precise

Profesional



Photo 28



Photo 29

Precise

Profesional



Photo 30



Photo 31



 
 Proper
 Precise
 Profesional

 Motor Vehicle Appraiser and Insurance Loss Adjuster
 Our Ref: 202303012



Photo 32



Photo 33

Precise

Proper

Profesional



Photo 34



Photo 35



Precise

Profesional



Photo 36



Photo 38



Profesional

 
 Proper
 Precise
 Profesional

 Motor Vehicle Appraiser and Insurance Loss Adjuster
 Our Ref: 202303012



Photo 39



Photo 40

Precise

Profesional



Photo 41



Photo 42

Precise

Profesional



Photo 43



Photo 44



Precise Proper



Photo 45