

Motorcycle Appraisal Service Pte Ltd  
UEN: 202221186K  
Email: MotorcycleAppraisalService@gmail.com  
Contact: 8800 8578

ACCIDENT DAMAGED VEHICLE INSPECTION REPORT

M/S :	RWAVE PTE LTD	Date	: 19 Oct 2022
	C/O RWAVE PTE LTD	Our Ref	: MAS/TP/2022-110
	50 Bukit Batok Street 23, Midview Building, #02-25		
	Singapore 659578		

REFERENCE PARTIFUCLARS

Date of Accident	: 04 Oct 2022	Type of Inspection	: Third Party Claim
Date of Inspection	: 06 Oct 2022	Date of Re-Inspn	: 18 Oct 2022

VEHICLE PARTICULARS

Registration No	: FBD6072H	Engine No	: 453010242
Make	: Yamaha	Chassis No	: 453010242
Model	: X1R 135 M	Odometer	: 40437km
Year	: 2009	Colour	: Black

CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine Condition	: Good	General Body Work:	Good
Foot Brake	: Serviceable	Steering	: Serviceable
Hand Brake	: Serviceable	Lightings	: Serviceable

TYRE CONDITION (Remaining estimated life of tyre in mm)

	<u>Make</u>	<u>Size</u>	<u>Thread Balance</u>
Front Side	: Maxxis	80/90/17	5 mm
Rear Side	: Maxxis	80/90/17	5 mm

GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained damage at the front and right side portion.  
For details, refer to assessment for repairs and photographs attached.

ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was S\$4,500.00 nett at lump sum basis.(Subject to GST if applicable)

Under normal circumstances, estimated period required for repairs : Ten ( 10 ) working days.

Enclosed Fifty Six ( 56 ) photographs depicting damage to the vehicle.

Inspection conducted at: RWAVE PTE LTD  
50 Bukit Batok Street 23, Midview Building, #02-25. Singapore 659578

In accordance to your instruction, we have **not authorized** repairs and inspection was conducted strictly on a "WITHOUT PREJUDICE BASIS".

Vehicle No : FBD6072H  
Model : X1R 135 M

Our Ref : MAS/TP/2022-110

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

DESCRIPTION OF PARTS AND NATURE OF REPAIRS						
S/ N	SPARE PARTS	QTY PC/SE T	ASSESSED CONDITION	ORIGINAL QUOTATIO N		REVISED QUOTATIO N
1	Headlamp	1 pcs	Dent	\$	500	\$ 450
2	Front Rim	1 pcs	Dent	\$	400	\$ 350
3	Front Rim Shaft	1 pcs	Dent	\$	120	\$ 80
4	Front Disc	1 pcs	Dent	\$	200	\$ 180
5	Front Fender	1 pcs	Cut	\$	120	\$ 100
6	Front Mask Coverset	1 pcs	Broken	\$	85	\$ 70
7	Front Mask V Plastic Cover	1 pcs	Cut	\$	80	\$ 65
8	Front Basket	1 pcs	Dent	\$	120	\$ 100
9	Front Left Signal	1 pcs	Cut	\$	150	\$ 120
10	Front Right Signal	1 pcs	Cut	\$	150	\$ 120
11	Left Mirror	1 pcs	Cut	\$	85	\$ 80
12	Right Mirror	1 pcs	Cut	\$	85	\$ 80
13	Handlebar	1 pcs	Dent	\$	220	\$ 180
14	Left Fork	1 pcs	Dent	\$	850	\$ 750
15	Right Fork	1 pcs	Dent	\$	650	\$ 400
16	Middle T Fork	1 pcs	Dent	\$	650	\$ 400
17	Front Left Plastic Cover	1 pcs	Cut	\$	150	\$ 120
18	Front Right Plastic Cover	1 pcs	Cut	\$	150	\$ 120
19	Exhuast	1 pcs	Dent	\$	800	\$ 750
			Total	\$	5565	\$ 4515
			Less 10%	\$	556.5	\$ 451.5
			Parts Sub Total	\$	5008.5	\$ 4063.5
<u>Special Nett Item</u>						
20	Steering cone	1 set	Necessary	\$	175	\$ 175
21	License Plate (Front)	1 pcs	Dent	\$	25	\$ 25
22	License Plate (Rear)	1 pcs	Dent	\$	25	\$ 25
23	Front Fork Oil	1 btl	Necessary	\$	50	\$ 50
			Total	\$	275	\$ 275
<u>LABOUR CHARGES &amp; MISC</u>						
1	Replace, realign and adjust above damage parts and check wiring and lightning system			\$	300	\$ 250
2	To knock, straighten chassis and body balancing			\$	350	\$ 250
3	To R&R front suspension, handle bar, headlamp, side fairing, and attachements			\$	300	\$ 250
4	To respray on accident affected area			\$	120	\$ 100
5	Towing Service			\$	120	\$ 80
			Total	\$	1190	\$ 930
			Sub Total	\$	6473.5	\$ 5268.5



**POINT OF IMPACT**

The impact was confined to the front and right side portion of the vehicle.  
The damages appeared to be consistent as per the accident report statement.  
Please refer the attached schedule and photographs for details.


**ADJUSTMENT/RECOMMENDATIONS**

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

**CONCLUSION**

The repairer has agreed to undertake repair the vehicle at a lump sum basis of S\$4,500.00 nett corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfully  
MOTORCYCLE APPRAISAL SERVICE

  
\_\_\_\_\_  
John Guo  
Automotive Appraiser











GENERAL  
INSURANCE

**IMPORTANT NOTE:** Please submit the completed Addendum form to the same Accident Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENOMENTS:

Original Report No: SE0P22A50001 Vehicle Registration No: SC69116

Name (as shown in NRIC): \_\_\_\_\_ NRIC/FIN/Passport No: \_\_\_\_\_

(\* Vehicle Driver/Vehicle Owner) ( \* ) Please delete as appropriate

Address: \_\_\_\_\_ Singapore ( )

Contact (Tel): \_\_\_\_\_ Mobile No.: \_\_\_\_\_

Email Address: \_\_\_\_\_

Date of Accident: 04/10/22 Time of Accident: 1135

Place of Accident: Long Kee Road

Insurance Company: Liberty

(B) ADDITIONAL INFORMATION /AMENDMENTS:

I have made a report on the above-mentioned accident and would like to include additional information or make the following amendments:

To amend the car plate

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Policyholder / Driver's Signature  
Date:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:  
Date:



**Enquire Vehicle's Insurance Particulars ( As At 04 Oct 2022 / 17:30:00 )**

Vehicle No.:

SCQ711G

Make Description/Model:

MINI / COOPER S COUNTRYMAN LED NAV  
SR

Insurance Company Name:

AIG ASIA PACIFIC INSURANCE PTE. LTD.

Business Transaction Reference No.:

20221006175808843469

Please retain the business transaction reference number for Enquire Vehicle Owner Details (if required).

*Printed on 06 Oct 2022 17:58:11*

*Copyright © Land Transport Authority of Singapore 2022*

## Enquire Vehicle Owner Details ( As At 04 Oct 2022 / 17:30:00 )

### Vehicle Owner Details

Owner ID Type:

Singapore NRIC

Owner ID:

S7131095G

Owner Name:

PON BOON CHUAN PATRIQUE

Registered Address Type:

Private Residential (Condo Apt or House) /  
Shopping / Office Complexes

Registered Block/House No.:

3

Registered Street Name:

ST. MICHAEL'S ROAD

Registered Unit No.:

# 25 - 06

Registered Building Name:

-

Registered Postal Code:

328007

### Vehicle Insurance Details

Vehicle No.:

SCQ711G

Make Description/Model:

MINI / COOPER S COUNTRYMAN LED NAV  
SR

Insurance Company Name:

AIG ASIA PACIFIC INSURANCE PTE. LTD.

RWAVE PTE LTD

CO REG. NO 201909822G EMAIL: RWAVEPTELTD@GMAIL.COM

INVOICE

50 BUKIT BATOK STREET 23  
#02-25 MIDVIEW BUILDING SINGAPORE 659578  
Contact: 9369 6861 / 9773 3456

DATE: October 20, 2022  
INVOICE # FBD6072H001  
FOR: FBD6072H

RE: Accident involving FBD6072H

DESCRIPTION	AMOUNT
LUMP SUM REPAIR (Inclusive of supplying parts and labour)	\$ 4,500.00
TOTAL	\$ 4,500.00

Make all checks payable to RWAVE PTE LTD  
If you have any questions concerning this invoice, contact James 93696861,  
rwavepteltd@gmail.com

RWAVE PTE LTD  
Reg. No. 201909822G

Issued by: James Chua

Motorcycle Appraisal Service Pte Ltd  
UEN: 202221186K  
Email: MotorcycleAppraisalService@gmail.com  
Contact: 8800 8578


---

Our Ref : MAS/TP/2022-110  
Invoice Ref : MAS/TP/2022-110  
Vehicle No : FBD6072H  
Attn : RWAVE PTE LTD  
Company : RWAVE PTE LTD  
Address : 50 Bukit Batok Street 23, Midview Building, #02-25 Singapore 659578

Invoice

Surveyor Fee	\$ 550
Re-inspection Fee	\$ 120
Transport	\$ 80
Photographs (@ \$1 per photo, total 56 photos)	\$ 56
Total:	\$ 806

Yours faithfully  
MOTORCYCLE APPRAISAL SERVICE

  
\_\_\_\_\_  
John Guo  
Automotive Appraiser



Motorcycle Appraisal Service Pte Ltd  
UEN: 202221186K  
Email: MotorcycleAppraisalService@gmail.com  
Contact: 8800 8578

ACCIDENT DAMAGED VEHICLE INSPECTION REPORT

M/S :	RWAVE PTE LTD	Date	: 19 Oct 2022
	C/O RWAVE PTE LTD	Our Ref	: MAS/TP/2022-110
	50 Bukit Batok Street 23, Midview Building, #02-25		
	Singapore 659578		

REFERENCE PARTIFUCLARS

Date of Accident	: 04 Oct 2022	Type of Inspection	: Third Party Claim
Date of Inspection	: 06 Oct 2022	Date of Re-Inspn	: 18 Oct 2022

VEHICLE PARTICULARS

Registration No	: FBD6072H	Engine No	: 453010242
Make	: Yamaha	Chassis No	: 453010242
Model	: X1R 135 M	Odometer	: 40437km
Year	: 2009	Colour	: Black

CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine Condition	: Good	General Body Work:	Good
Foot Brake	: Serviceable	Steering	: Serviceable
Hand Brake	: Serviceable	Lightings	: Serviceable

TYRE CONDITION (Remaining estimated life of tyre in mm)

	<u>Make</u>	<u>Size</u>	<u>Thread Balance</u>
Front Side	: Maxxis	80/90/17	5 mm
Rear Side	: Maxxis	80/90/17	5 mm

GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained damage at the front and right side portion.  
For details, refer to assessment for repairs and photographs attached.

ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was S\$4,500.00 nett at lump sum basis.(Subject to GST if applicable)

Under normal circumstances, estimated period required for repairs : Ten ( 10 ) working days.

Enclosed Fifty Six ( 56 ) photographs depicting damage to the vehicle.

Inspection conducted at: RWAVE PTE LTD  
50 Bukit Batok Street 23, Midview Building, #02-25. Singapore 659578

In accordance to your instruction, we have **not authorized** repairs and inspection was conducted strictly on a "WITHOUT PREJUDICE BASIS".

Vehicle No : FBD6072H  
Model : X1R 135 M

Our Ref : MAS/TP/2022-110

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

DESCRIPTION OF PARTS AND NATURE OF REPAIRS						
S/ N	SPARE PARTS	QTY PC/SE T	ASSESSED CONDITION	ORIGINAL QUOTATIO N		REVISED QUOTATIO N
1	Headlamp	1 pcs	Dent	\$	500	\$ 450
2	Front Rim	1 pcs	Dent	\$	400	\$ 350
3	Front Rim Shaft	1 pcs	Dent	\$	120	\$ 80
4	Front Disc	1 pcs	Dent	\$	200	\$ 180
5	Front Fender	1 pcs	Cut	\$	120	\$ 100
6	Front Mask Coverset	1 pcs	Broken	\$	85	\$ 70
7	Front Mask V Plastic Cover	1 pcs	Cut	\$	80	\$ 65
8	Front Basket	1 pcs	Dent	\$	120	\$ 100
9	Front Left Signal	1 pcs	Cut	\$	150	\$ 120
10	Front Right Signal	1 pcs	Cut	\$	150	\$ 120
11	Left Mirror	1 pcs	Cut	\$	85	\$ 80
12	Right Mirror	1 pcs	Cut	\$	85	\$ 80
13	Handlebar	1 pcs	Dent	\$	220	\$ 180
14	Left Fork	1 pcs	Dent	\$	850	\$ 750
15	Right Fork	1 pcs	Dent	\$	650	\$ 400
16	Middle T Fork	1 pcs	Dent	\$	650	\$ 400
17	Front Left Plastic Cover	1 pcs	Cut	\$	150	\$ 120
18	Front Right Plastic Cover	1 pcs	Cut	\$	150	\$ 120
19	Exhuast	1 pcs	Dent	\$	800	\$ 750
			Total	\$	5565	\$ 4515
			Less 10%	\$	556.5	\$ 451.5
			Parts Sub Total	\$	5008.5	\$ 4063.5
<u>Special Nett Item</u>						
20	Steering cone	1 set	Necessary	\$	175	\$ 175
21	License Plate (Front)	1 pcs	Dent	\$	25	\$ 25
22	License Plate (Rear)	1 pcs	Dent	\$	25	\$ 25
23	Front Fork Oil	1 btl	Necessary	\$	50	\$ 50
			Total	\$	275	\$ 275
<u>LABOUR CHARGES &amp; MISC</u>						
1	Replace, realign and adjust above damage parts and check wiring and lightning system			\$	300	\$ 250
2	To knock, straighten chassis and body balancing			\$	350	\$ 250
3	To R&R front suspension, handle bar, headlamp, side fairing, and attachments			\$	300	\$ 250
4	To respray on accident affected area			\$	120	\$ 100
5	Towing Service			\$	120	\$ 80
			Total	\$	1190	\$ 930
			Sub Total	\$	6473.5	\$ 5268.5

**POINT OF IMPACT**

The impact was confined to the front and right side portion of the vehicle.  
The damages appeared to be consistent as per the accident report statement.  
Please refer the attached schedule and photographs for details.


**ADJUSTMENT/RECOMMENDATIONS**

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

**CONCLUSION**

The repairer has agreed to undertake repair the vehicle at a lump sum basis of S\$4,500.00 nett corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfully  
MOTORCYCLE APPRAISAL SERVICE

  
\_\_\_\_\_  
John Guo  
Automotive Appraiser







