

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 8873C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DEFORMED	481.10	481.10
1	FRONT BUMPER UPPER MOULDING	сит	368.50	368.50
10	FRONT BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	FRONT BUMPER SIDE BRKT LH	DEFORMED	35.00	35.00
1	FRONT WHEEL RIM LH	NOT NECESSARY	1,124.20	-
1	FRONT FENDER LH	BENT	588.80	588.80
1	FRONT FENDER (BLUE-DRIVE) LH	NECESSARY	26.60	26.60
1	FRONT FENDER SHIELD LH	NOT NECESSARY	164.70	-
1	HEADLAMP LH	CRACKED	2,110.30	2,110.30
1	DAYLIGHT LH	NOT NECESSARY	642.50	-
1	DAYLIGHT GRILLE LH	NOT NECESSARY	93.45	-
1	BONNET	BENT	2,253.80	2,253.80
1	WING MIRROR GARNISH LH	MISSING	64.10	64.10
	LESS 20% DISCOUNT		-1,595.01	-1,190.04
			6,380.04	4,760.16
	SPECIAL NETT ITEMS			
1	FRONT FENDER ADV.STICKER LH (SN)	NECESSARY	100.00	100.00
			100.00	100.00
	LABOUR			
	PANEL BEATING.		800.00	525.00
	SPRAY PAINTING.		900.00	750.00
	CHECK WIRINGS.		40.00	30.00
	TUFF KOTE.		60.00	30.00
	WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
			1,920.00	1,335.00
	GRAND TOTAL		8,400.04	6,195.16





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		4,950.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC23006393/Tnp3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser