

PRE-REPAIR SURVEY REPORT

NTUC Income Insurance Co-operative Ltd

73 Bras Basah Road #05-01 NTUC Trade Union House Singapore 189556

Attention: Mr Steven Saw

Assign Date:

17/10/2018

Survey Date: TP Policy No: 17/10/2018

Adjustment Date: 06/11/2019

Accident Date: Place of Survey: 12/10/2018 Moto-51

NA

Our Ref: Your Ref: AVS2018-16512/BL MT/1015474-003

464 MacPherson Rd 368182 Singapore

Claim Type: Claimant:

Third Party Salim Bin Salleh

Description of Vehicle:

Veh. No:

FN9068B Blue

Make/Model:

Honda CB400SF

Colour: **Engine Capacity:**

399 cc 4149

Engine No:

NC23E1701310 NC311401303

Chassis No: Reg. Date:

20/11/1996

Condition of Vehicle:

General:

Odometer:

Good

Modification: Footbrake:

No

Steering:

Paint work:

Affected

Handbrake: Tyre Make:

Affected

Pirelli

Front Side:

4mm

Affected

Good

Front Tyre Size: Rear Tyre Size:

120/70R17 120/70R17

Rear Side:

4mm

Description of Damage:

The vehicle sustained damage on the front and left portions.

The front fork, front side mirror, side crush bar and rear box were among the items affected.

Remarks:

Our recommended amount for the cost of contract lumpsum repair is \$\$2,100.00 with approximately three (3) working days to complete. However, no finalisation was agreed with the repairer.

Adjuster: Billy Loh Motor Appraiser COMPLETED 07 NOV 2019

Date

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.



| djustn | nent of F | Repair Cost for Vehicle: | FN9068B | Our Ref: | 377 |
|----------|-----------|--------------------------------|-----------------------|---|------------------------------|
| No. | Qty | Description of Parts | Condition | Third Party Surveyor's Estimate S\$ | Our Recommendation S\$ |
| ist Iten | ns | | | | |
| 1 | 2 | Brake disc R/L @ \$490.00 | Not necessary | 490.00 | - |
| 2 | 1 | Brake pedal | Not necessary | 130.00 | |
| 3 | 1 | Brake lever | Not necessary | 75.00 | |
| 4 | 1 | Exhaust muffler | Not necessary | 1,650.00 | |
| 5 | 1 | Fork bottom bracket | Bent | 285.00 | 285.00 |
| 6 | 2 | Fork inner tube R/L @ \$226.00 | Bent | 452.00 | 452.00 |
| 7 | 1 | Fork top bracket | Bent | 335.00 | 335.00 |
| 8 | 1 | Front fender | Not necessary | 145.00 | 227 |
| 9 | 2 | Front footrest R/L @ \$85.00 | Not necessary | 85.00 | 85.00 |
| 10 | 2 | Front signal R/L @ \$65.00 | Cut | 65.00 | 65.00 |
| 11 | 1 | Front under cover | Not necessary | 117.00 | 22.5 |
| 12 | 1 | Front wheel rim | Not necessary | 980.00 | 750 |
| 13 | 1 | Front wheel rim shaft | Not necessary | 96.00 | |
| 14 | 1 | Fuel tank assy | Not necessary | 22 | 220 |
| 15 | 1 | Handle bar | Not necessary | 165.00 | |
| 16 | 2 | Mirror assy R/L @ \$75.00 | Cut | 150.00 | 75.00 |
| 17 | 2 | Rear footrest R/L @ \$85.00 | Not necessary | | |
| 18 | 1 | Rear mudguard | Cut | 145.00 | 145.00 |
| 19 | 2 | Rear signal R/L @ \$65.00 | Cracked | 130.00 | 65.00 |
| 20 | 1 | Taillamp assy | Not necessary | | |
| | | | Sub Total: | 5,495.00 | 1,507.00 |
| | | | Discount (less 10%): | 549.50 | 150.70 |
| | | | 25 50 | 4,945.50 | 1,356.30 |

| Special Nett Items | | | | | |
|--------------------|-------|------------------------------|---------------|--------|--------|
| 1 | 1 set | Body safety guard | Grazed | 550.00 | 350.00 |
| 2 | 2 | Fork oil seal R/ L @ \$32.00 | Necessary | 64.00 | 40.00 |
| 3 | 1 set | Front wheel bearing | Not necessary | 85.00 | |

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd



| djustn | nent of R | sepair Cost for Vehicle: | FN9068B | Our Ref: | AVS2018-16512/BL |
|--------|-----------|--------------------------|--------------------|---|------------------------------|
| No. | Qty | Description of Parts | Condition | Third Party Surveyor's Estimate S\$ | Our Recommendation S\$ |
| 4 | 1 set | Handle bar grip | Cut | 70.00 | 35.00 |
| 5 | | Rear box | Cut | 380.00 | 280.00 |
| 6 | 1 | Rear boc bracket | Bent | 160.00 | 120.00 |
| 7 | 1 | Rear no plate | Bent | 25.00 | 20.00 |
| 8 | 1 | Sterring cone/ bearing | Necessary | 95.00 | 80.00 |
| | | *** | Sub Total: | 1,429.00 | 925.00 |
| | | | Total Parts Price: | 6,374.50 | 2,281.30 |

| 1 | To remove, reinstall electircal wiring harness, check lighting. (to FR) | 30.00 | 20.00 |
|---|---|----------|----------|
| 2 | To re-sprat painting on the change bodyparts, repair portion and where consistent to the repair. | 350.00 | 200.00 |
| 3 | To provide labour, workmanship change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignment and damaged consistent to the accident. | 300.00 | 200.00 |
| 4 | To straighten body frame to the original position. | 250.00 | |
| | Sub Total: | 930.00 | 420.00 |
| | Grand Total: | 7,304.50 | 2,701.30 |





PRE-REPAIR SURVEY REPORT

NTUC Income Insurance Co-operative Ltd

73 Bras Basah Road #05-01 NTUC Trade Union House Singapore 189556

Attention: Mr Marcus Xiao

Assign Date: Accident Date: 17/10/2018 12/10/2018

Survey Date: TP Policy No: 17/10/2018

Our Ref:

AVS2018-16512/BL

Place of Survey: Moto-51

Your Ref:

MT/1015474-002

464 MacPherson Rd 368182

Singapore

Claim Type:

Third Party

Description of Vehicle:

Veh. No:

FN9068B

Make/Model:

Honda CB400SF

Colour: **Engine Capacity:** Blue NA

Engine No:

NA

Odometer:

4149

Chassis No: Reg. Date:

NΔ NΔ

Condition of Vehicle:

General:

Good

Modification:

No

Steering:

Affected

Handbrake: Tyre Make:

Affected

Pirelli

120/70R17

Front Side:

Footbrake:

4mm

Affected

Paint work:

Good

Front Tyre Size: Rear Tyre Size:

120/70R17

Rear Side:

4mm

Description of Damage:

The vehicle sustained damage on the front and left portions.

The front fork, front side mirror, side crush bar and rear box were among the items affected.

Remarks:

Based on visual survey of the vehicle without any repair estimate provided, we viewed that the repair cost should not be more than \$\$1,000.00 and could take approximately three (3) working days to complete.

Adjuster:

Motor Appraiser

COMPLETED 12 NOV 2018

Date

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

Our Ref: Your Ref: AVS2018-16512/BL MT/1015474-002

Pre-repair survey - 17/10/2018













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

Our Ref: AVS2018-16512/BL Your Ref:

MT/1015474-002


Pre-repair survey













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

Our Ref: Your Ref: AVS2018-16512/BL MT/1015474-002

Pre-repair survey

Re-survey items - 28/10/2018













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

Our Ref:

AVS2018-16512/BL

Your Ref:

ef: MT/1015474-002 Re-survey items













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

Our Ref: AVS2018-16512/BL Your Ref: MT/1015474-002 Post repair survey - 02/11/2018













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd