

# COZON ENGINEERS

Blk 206A Compassvale Lane #02-77 Singapore 541206

UEN: 53206579D

## ACCIDENT VEHICLE DAMAGE ASSESSMENT REPORT

Our reference no.: 23-20069

Date: 9/5/2023

"Without Prejudice"

### DESCRIPTION / IDENTIFICATION OF VEHICLE

Registration No:	SMG8080A	Make:	Mercedes Benz
Register Owner:	Lee Tong Hai	Model:	E200 SEDAN (R18)
Chassis Number:	WDD2120342A859387	Transmission:	Auto
Colour:	Black	Odometer:	206188km

### STATIC CHECK

Steering:	In order	Paintwork:	Good
Handbrake:	In order	General Condition:	Good
Foot Brake:	In order		

### CONDITION OF TYRES


Front Tyre Size:	245/40ZR18		
Front Left Side:	85% Westlake	Front Right Side:	85% Westlake
Rear Tyre Size:	245/40ZR18		
Rear Left Side:	85% Westlake	Rear Right Side:	85% Westlake

### INSPECTION

Date of inspection:	20/1/2023	Date of Accident:	17/1/2023
---------------------	-----------	-------------------	-----------

### AREA & DIRECTION OF IMPACT

Enclosed photographs for more detail of the damages.



In view of the age of the said vehicle and with my professional opinion, the repair cost recommended at  
with number of working days for repair estimated at 3

\$1,700.00

**Tan LL** (Automotive Appraiser)

NTC-3 (Motor Vehicle Mechanic)

NTC-2 (Automotive Technology)

Certificate from Vocational Institute (Anti-skid Brake System)

Trainer of Institute of the Motor Industry, UK

Enterprise Singapore - Recognised Certification for Management Consultants

# COZON ENGINEERS

Blk 206A Compassvale Lane #02-77 Singapore 541206  
UEN: 53206579D

Our reference no.: 23-20069

Date: 9/5/2023

## Parts Assessment

Parts Description	Qty	Condition	Workshop's Estimate	Our Adjustment
-------------------	-----	-----------	---------------------	----------------

### List Items:

Front door lh - slightly dented	1	repair	1951.00	0.00	✗ R
Front door outer moulding top lh	1	dented	188.90	188.90	✗ nn
Front door outer handle lh	1	dented	232.00	232.00	✗ R
Side mirror motor lh	1	broken/malfunction	560.00	560.00	✓
Side mirror lower cover lh	1	cracked	112.10	112.10	✓
Side mirror glass lh	1	broken	185.60	185.60	✓
Side mirror signal lamp with cover lh	1	cracked	286.50	286.50	✓
<b>Sub- Total</b>			3516.10	1565.10	1144.20
<b>Parts discount :</b> 10%			351.61	156.51	-10%
<b>Sub-Total costs for parts</b>			<b>3164.49</b>	<b>1408.59</b>	<b>1029.78</b>

### Special Nett Items:

*	*	*	*
<b>Sub-Total cost for parts</b>		<b>0.00</b>	<b>0.00</b>
<b>Total cost for parts</b>		<b>3164.49</b>	<b>1408.59</b>

# COZON ENGINEERS

Blk 206A Compassvale Lane #02-77 Singapore 541206  
UEN: 53206579D

Our reference no.: 23-20069

Date: 9/5/2023

## Labour Assessment

Description	Workshop's Estimate	Our Adjustment
To dismantle, replace, cut, weld, knock out dents to straighten accident damaged parts	400.00	380.00 200
To putty & spray paint accident damaged parts and adjacent panels	500.00	350.00 100
To apply rust proofing on accident damaged parts and adjacent panels	40.00	20.00 X
Wiring /bulb checking/focusing	40.00	20.00 ✓
<b>Total cost for Labour</b>	<b>980.00</b>	<b>770.00 320</b>

## Adjusted Repair Cost

			1349.78
		2 days	
<b>Total cost for Parts</b>	<b>3,164.49</b>	<b>1,408.59</b>	<b>L/S - 1079.82 = 1100</b>
<b>Total cost for Labour</b>	<b>980.00</b>	<b>770.00</b>	
<b>Total cost for Parts &amp; Labour</b>	<b>4,144.49</b>	<b>2,178.59</b>	

The recommended cost of repairs based on lump sum repairs is : \$1,700.00  
and the recommended number of working days for the repair is : 3