

YEW TEE AUTOMOBILE TECH PTE LTD

39 WOODLANDS CLOSE #01-12 MEGA@WOODLANDS S(737856)

25 KAKI BUKIT ROAD 4 #01-61 SYNERGY@KB S(417800)

To: China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road #16-00 Springleaf Tower
Singapore 079909

DATE: 27/06/2023

Dear Sir / Madam:

RE: VEHICLE REPAIR ESTIMATE

Owner : KHOZEM ZAKI UDDIN DARUWALA

Model : HONDA CITY

Reg : 21/01/2011

Chassis : MRHGM26709P020534

DOAccident : 18/06/2023

THIRD PARTY CLAIM AGAINST

We are please to submit our estimate of repairs to the above mention vehicle.

		Parts	Labour
1	Front bumper	\$ 420.00	de ✓ \$420.00
2	Front headlamp RH	\$ 510.00	an ✓ \$410.00
3	Front fender RH	\$ 360.00	bt ✓ \$300.00
4	Front rim RH	\$ 750.00	ant ✓ \$600.00
5	Front bonnet	\$ 750.00	X nn
6	Front fender inner shield RH	\$ 75.00	de ✓ \$75.00
7	Front fog lamp RH	\$ 510.00	X nn
8	Front fog lamp cover RH	\$ 75.00	X nn
9	Front bumper side retainer RH	\$ 90.00	de ✓ 30.00
Total Parts		\$ 3,705.00	\$1835.00
Less	20%	\$ 741.00	\$367.00
		\$ 2,964.00	\$1468.00
11	Front fender inner shield clip	\$ 30.00	20ner ✓ \$20.00
12	Front bumper sensor	\$ 200.00	X nn
13	Front bumper clip	\$ 30.00	ney ✓ \$30.00
14	To spray painting on the replaced and repair parts, prepare spray such as masking tape the unaffected areas with paper cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 600.00	480 \$400.00
15	To remove and replace the above damaged parts, straighten knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 480.00	300 \$300.00
16	To apply undercoating on the repaired and replaced panels for rust protection.		
17	To dismantle and refit front undercarriage.	\$ 120.00	X nn
18	To remove and refit front bumper sensor.	\$ 80.00	X nn
19	To computer wheel alignment	\$ 100.00	80 \$80.00
Labour Total:		\$ 1,640.00	\$830.00

Tanflin 9249 5749 / 62565561
"wp" 26/6/23C / ph
LBS Res my after repair
tanflin C Thhants.com
3 days

Grand Total : \$ 4,604.00 \$2298.00

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.

Shaun : 97432262

PARTS: \$1468.00
LABOUR: \$830.00
LESS 20% : \$459.60
TOTAL: \$1838.40
ROUND UP: \$1800.00
L/S\$1800, 3 DAYS #