PAS

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191. Mobile: 9295-2204 Fax: 6722-8508 Email: pasvos@hotmail.com

Business Reg. 201404434D

## VEHICLE INSPECTION REPORT

Report No.: PAS/TP/0410123 Date of Report : 22/02/2023

To: M/s. ComfortDelGro Rent-A-Car Pte Ltd Date of Assignment #31/01/2023

C/o. 160 Sin Ming Drive Report requested by #05-08 Sin Ming Autocity Date of Accident : 25/01/2023

Singapore 575722 Date of Inspection : 31/01/2023
Claim No. : Third Party Claim

Policy No. : -

#### PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. : SNC819Z Engine Capacity (cc) : 1797

Make & Model: Toyota Noah (Hybrid)Mileage (km): 96619kmDate of Registration: 28/09/2021Chassis / Frame No.: ZWR800504928Colour: Met. SilverEngine No.: 2ZR2M74527

### TYRE CONDITION

Front LH : 7 mm Front RH : 7 mm

Make : Davanti Make : Davanti

Rear LH : 7 mm Rear RH : 7 mm Make : Davanti Make : Davanti

Road wheels Type: Alloy

(The above represents the approximate remaining life of tyre treads)

## PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork : Good
Paintwork : Good
Handbrake : Serviceable
Footbrake : Serviceable
Steering : Serviceable

Apparent Engine Modification Nil

## PLACE OF REPAIRER OFFICE/WORKSHOP

Location : M/s. Kum Chew Motor Workshop

160, Sin Ming Drive, #05-08, Sin Ming Autocity, Singapore 575722

### ASSESSMENT

Repairer's Estimate : \$ 3,987.20 Revised Amount : \$ 2,825.25

Less Excess : \$

Recommended Reserve : \$ 2,260.00 (Lump Sum)

Estimated Normal Period of Repairs : 4 Working Days

**Disclaimer:** The information contained in this report is intended for exclusive use of the addresses (including any attachments) solely in relation to the loss occurrence in which the assessed vehicle involved. It is confidential and may protected by legal privileged. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party. If you are not the intended recipient, please contact us immediately to arrange for its return and you should not disseminate, distribute, copy any information contained herein or use of this communication is strictly prohibited.



Correspondence Mail Address: My Mail Box 886259 Singapore 919191. Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No: SNC819Z

**Report No. : PAS/TP/0410123** 

## **GENERAL REMARKS**

WITHOUT PREJUDICE

#### THE ASSIGNMENT

The survey was conducted at M/s. Kum Chew Motor Workshop, 160, Sin Ming Drive, #05-08, Sin Ming Autocity, Singapore 575722.

(Subsequent inspections have been conducted)

### POINT OF IMPACT

At the rear RH portion.

#### DAMAGES

The tailgate, rear bumper, RHR side bumper, rear end panel, RHR fender, etc.

Other parts were also found damaged. (See schedule for details)

### ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$2,825.25.

## CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$2,260.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,

Prominent/Appraiser Services Pte Ltd

Andrew How

**Automobile Appraiser** 

**MSAAA** 

Licensed Appraiser

Qualified Loss Adjusters And Motor Appraisers
Correspondence Mail Address: My Mail Box 886259 Singapore 919191
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Vehicle No: SNC819Z

Business Reg. 201404434D

Report No. : PAS/TP/0410123

# APPRAISEMENT SCHEDULE

	Qty	Parts Descriptions	Condition			Repairer's Estimate (S\$)		Our Assessment (S\$)		
1	1 nc	Rr bumper (w/col.)	Dented/Deformed			\$	1,578.00	\$	1,578.00	985 v
2		Rr bumper side R/L	Cracked/Deformed	\$	178.60	\$	357.20	\$		X nn
3		Rr bumper reflector RH	Loop Broken		1.0.00	\$	75.20	\$	75.20	
4		Rr bumper clip	Necessary	\$	3.20	\$	19.20	\$	19.20	
5		Rr bumper retainer R/L	Cracked/Necessary	\$	89.20	\$	178.40	\$	178.40	
6		Rr bumper side support RH	Dented			\$	92.33	\$	92.33	
7		Rr end panel assy	Dented/Repair			\$	802.60	\$	-	
8	1 pc	Tailgate Tailgate	Dented/Repair			•		efer labour	no. 2 & 3)	
9	1 pc	Rr fender RH	Dented/Repair				(Refer labour no. 2 & 3)			
10	1 pc	tr end panel assy  Dented/Repair  (Refer labour no. 2 & 3								
	r		•			\$	3,102.93	-\$	2,300.33	-
			1350.13	Less I	Discount: 25%		775.73	25% \$	575.08	
			-25% 1012.59 <sup>List</sup>		ub-Total :	\$	2,327.20	\$	1,725.25	=
				Par	ts Total :	\$	2,327.20	\$	1,725.25	
						Est	timate (S\$)	A33C331	nent (S\$)	
1	To remo	ove and reinstall electrical wiring	system for necessary rep.	airs.		ESI	imate (S\$)	Assessi	nent (34)	
,	To chec	ove and reinstall electrical wiring k rear electrical wiring system. sfer rear reverse sensors to new b		airs,		Esi \$	60.00	Assessi \$	50.00	30
2	To chec To trans To remo	k rear electrical wiring system.	umper. s, garnishes, etc. for nece	essary re	epairs.					
2	To chec To trans To remo	k rear electrical wiring system. sfer rear reverse sensors to new b ove and reinstall rear interior trim ghten, repair, realign on affected	umper. s, garnishes, etc. for nece area and replace damaged	essary re	epairs.	\$	60.00	\$	50.00	300
2	To chec To trans To remo	k rear electrical wiring system.  sfer rear reverse sensors to new b  ove and reinstall rear interior trim	umper. s, garnishes, etc. for nece area and replace damaged	essary re d parts.		\$ \$ \$	60.00 800.00 800.00	\$ \$ \$	50.00 400.00 650.00	300
2	To chec To trans To remo	k rear electrical wiring system. sfer rear reverse sensors to new b ove and reinstall rear interior trim ghten, repair, realign on affected	umper. s, garnishes, etc. for nece area and replace damaged	essary re d parts.	epairs. ur Total :	\$	60.00	\$	50.00	300
2	To chec To trans To remo	k rear electrical wiring system. sfer rear reverse sensors to new b ove and reinstall rear interior trim ghten, repair, realign on affected	umper.  s, garnishes, etc. for nece area and replace damaged nd adjacent area.	essary re d parts. Labou		\$ \$ \$	60.00 800.00 800.00	\$ \$ \$	50.00 400.00 650.00	300
2	To chec To trans To remo	k rear electrical wiring system. sfer rear reverse sensors to new b ove and reinstall rear interior trim ghten, repair, realign on affected	umper.  s, garnishes, etc. for nece area and replace damaged nd adjacent area.	essary re d parts. Labou	ur Total :	\$ \$ <b>\$</b>	60.00 800.00 800.00 <b>1,660.00</b>	\$ \$ \$	50.00 400.00 650.00 1,100.00	300

Under normal circumstances, the repairs should be completed within a reasonable period

of 4 Working Days. (Exclude waiting days of PRI, Sunday, Pubic Holiday and awaiting of shipment for spare parts)

20 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall has the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.

Note: The revised estimate has been adjusted from a visual inspection. Any discrepancies or unseen damages should be notified to the company within 7 days from the date hereof. Otherwise this revised amount shall be deemed as valid.