



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 7770P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FENDER SUB ASSY RH	BENT	1,111.93	1,111.93
1	FRONT FENDER HYBRID EMBLEM RH	NECESSARY	86.50	86.50
1	FRONT FENDER SHIELD RH	TORN	198.50	198.50
1	FRONT BUMPER COVER	TORN	586.18	586.18
1	FRONT BUMPER SIDE BRACKET RH	DEFORMED	82.30	82.30
10	FRONT BUMPER CLIPS	NECESSARY	22.00	22.00
1	HEADLAMP RH	NOT NECESSARY	2,735.28	-
1	FRT BUMPER SIDE GRILLE RH	NOT NECESSARY	85.10	-
1	WHEEL RIM FRT RH	DENTED	1,570.55	1,570.55
	LESS 25% DISCOUNT		-1,619.59	-914.51
			4,858.75	2,743.45
	<u>LABOUR</u>			
	PANEL BEATING.		750.00	350.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	CHECK LIGHTING.	NOT NECESSARY	60.00	-
	TUFF KOTE.		60.00	30.00
			1,470.00	880.00
	GRAND TOTAL		6,328.75	3,623.45
	RECOMMENDED COST OF REPAIRS (CONFIRMED)			3,623.45

Report Ref No. NS/INC23006479/Tvp3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.