



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 3241B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BUMPER ASSY	TO REPAIR SEE LABOUR	481.10	-
10	FRT BUMPER CLIPS	NECESSARY	22.00	22.00
1	RADIATOR GRILLE	NOT NECESSARY	1,568.60	-
1	FRT BUMPER CENTRE MOULDING	CUT	368.50	368.50
1	RADIATOR GRILLE EMBLEM	NOT NECESSARY	31.30	-
	LESS 20% DISCOUNT		-494.30	-78.10
			1,977.20	312.40
	<u>SPECIAL NETT ITEMS</u>			
1	FRT NUMBER PLATE (SN)	CRACKED	55.00	55.00
			55.00	55.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRT BUMPER ASSY.		400.00	350.00
	SPRAY PAINT.		300.00	250.00
			700.00	600.00
	GRAND TOTAL		2,732.20	967.40

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			750.00
---	--	--	---------------

Report Ref No. NS/INC23006481/Tnp3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.