

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





AUTOMOBILE INSPECTION REPORT						
INCOME INSURANCE LTD			Ref:	NS/INC23006481/Tnp3m4		
75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Date:	05-07-2023 INC4		
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJL 6227S	Veh. Ir	spected	SHA 3241B	
	Policy No.		Covera	age (\$)	0.00	
	Claim No.	MT/1228983-002	Exces	s (\$)	0.00	
	Assign From		Assign	n Date	26/06/2023	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI IONIQ	c.c		1580	
	Engine No.	HIDDEN	Year o	f Reg.	2021	
	Chassis No.	KMHC851CVLU192321	Coloui	•	BLUE	
	Odometer	195693	Steeri	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	WEST	_AKE	6 mm	
	L/H Front Tyre	195/65 R15	WEST	_AKE	6 mm	
	R/H Rear Tyre	195/65 R15	WEST	_AKE	6 mm	
	L/H Rear Tyre	195/65 R15	WEST	_AKE	6 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5. General Information						
	Accident Date	23/06/2023	Inspec	tion Date	26/06/2023	
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD					
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	n. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					