

**MODERN AUTOMOTIVE PTE LTD**  
**BLK 3023A UBI ROAD 1 # 01-61**  
**SINGAPORE 408717**

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

Lonpac Insurance Bhd  
 300 Beach Road #17-04/07  
 The Concourse  
 Singapore 199555  
 Tel: 6250 7388  
 Fax: 6296 2706

**QUOTATION**  
 DATE : 03.07.2023  
 VEH NO : GBK1026M  
 MODEL : Toyota Dyna  
 D O A : 15.06.2023  
 YR REF : Own Damage

Attn : Motor Claims Dept

**RE : ESTIMATE FOR ACCIDENT REPAIR GBK1026M (TOYOTA DYNA)**

| Item | Description                                              | Qty | Amt                 |
|------|----------------------------------------------------------|-----|---------------------|
| 1    | Front Bumper <i>Distorted</i>                            | 1   | 255.00 ✓            |
| 2    | Front Bumper Bracket - LH & RH <i>LH Bent, RH?</i>       | 2   | 190.00 <i>95</i>    |
| 3    | Fog Lamp - LH & RH <i>LH cut</i>                         | 2   | 195.00 <i>97.50</i> |
| 4    | Head Lamp - LH & RH <i>LH cracked, RH cut</i>            | 2   | 520.00 ✓            |
| 5    | Front Grille ?                                           | 1   | 195.00              |
| 6    | Front Grille Clips ?                                     | 1   | 5.00                |
| 7    | Front Grille Logo ?                                      | 1   | 30.00               |
| 8    | Front Corner Panel - LH & RH <i>LH distorted, RH Rys</i> | 2   | 196.00 <i>98</i>    |
| 9    | Front Corner Panel Bracket - LH & RH <i>LH missing</i>   | 2   | 76.00 <i>38</i>     |
| 10   | Front Windscreen <i>cracked</i>                          | 1   | 390.00 ✓            |
| 11   | Front Windscreen Moulding <i>new</i>                     | 1   | 82.00 ✓             |
| 12   | Front Windscreen Pillar - LH <i>Dented</i>               | 1   | 215.00 ✓            |
| 13   | Front Wiper Arm - LH <i>new</i>                          | 1   | 65.00 <i>x</i>      |
| 14   | Front Wiper Blade - LH <i>cut</i>                        | 1   | 35.00 ✓             |
| 15   | Front Door - LH <i>Distorted</i>                         | 1   | 590.00 ✓            |
| 16   | Front Door Lock - LH <i>Jam</i>                          | 1   | 125.00 ✓            |
| 17   | Front Door Weatherstripe - LH ?                          | 1   | 80.00 ?             |
| 18   | Front Door Inner Trim Board - LH <i>Deh d</i>            | 1   | 350.00 ✓            |
| 19   | Front Door Inner Trim Board Clips - LH <i>new</i>        | 1   | 5.00 ✓              |
| 20   | Front Door Glass - LH <i>Shattered</i>                   | 1   | 225.00 ✓            |
| 21   | Front Door Glass Outer Moulding - LH <i>cut</i>          | 1   | 58.00 ✓             |
| 22   | Front Door Glass Regulator Gear - LH ?                   | 1   | 118.00 ?            |
| 23   | Front Door Signal Lamp - LH <i>cut</i>                   | 1   | 28.00 ✓             |
| 24   | Front Wheel ARC Panel                                    | 1   | 650.00              |
| 25   | Front Wheel ARC Panel Garnish <i>Deh d</i>               | 1   | 220.00 ✓            |
| 26   | Wing Mirror Assy (Auto) <i>missing Distorted</i>         | 1   | 425.00 ✓            |
| 27   | Front Door Pillar ?                                      | 1   | 1,180.00 ?          |
| 28   | Front Door Rear Panel - LH <i>Rys</i>                    | 1   | 308.00 <i>x</i>     |
| 29   | Front Step Panel - LH <i>? Distorted</i>                 | 1   | 125.00 ✓            |
| 30   | Front Step Panel Garnish - LH                            | 1   | 35.00 ✓             |

**RE : ESTIMATE FOR ACCIDENT REPAIR GBK1026M (TOYOTA DYNA)**

|    |                                        |            |       |          |            |
|----|----------------------------------------|------------|-------|----------|------------|
| 31 | Front Wheel Mud Shield - LH            | Dented     | 1     | 68.00    | ✓          |
| 32 | Front Wheel Mud Shield Clips - LH      | new        | 1     | 5.00     | ✓          |
| 33 | Air Con Condenser (Assy)               | Distorted  | 1 set | 550.00   | ✓          |
| 34 | Front Door - RH                        | Dented     | 1     | 590.00   | ✓          |
| 35 | Front Door Lock - RH                   | Dented new | 1     | 125.00   | x          |
| 36 | Front Door Weatherstripe - RH          | ?          | 1     | 80.00    | ?          |
| 37 | Front Door Inner Trim Board - RH       | ?          | 1     | 350.00   | ?          |
| 38 | Front Door Inner Trim Board Clips - RH | ?          | 1     | 5.00     | ?          |
| 39 | Front Door Glass - RH                  | cut        | 1     | 225.00   | ✓          |
| 40 | Front Door Glass Outer Moulding - RH   | new        | 1     | 58.00    | x          |
| 41 | Front Signal Lamp - RH                 | new        | 1     | 28.00    | x          |
| 42 | Wing Mirror - RH                       | Dented     | 1     | 105.00   | ✓          |
| 43 | Front Door Rear Panel - RH             | Dented     | 1     | 308.00   | ✓          |
| 44 | Front Step Panel - RH                  | new        | 1     | 125.00   | x          |
| 45 | Front Step Panel Garnish - RH          |            | 1     | 35.00    | x          |
| 46 | Roof Panel                             | Repair     | 1     | 450.00   | x          |
| 47 | Roof Panel Inner Trim Board            | crumpled   | 1     | 560.00   | ✓          |
| 48 | Roof Panel Inner Trim Board Clips      | new        | 1     | 5.00     | ✓          |
| 49 | Dashboard                              | ?          | 1     | 530.00   | ?          |
| 50 | Radiator                               | ?          | 1     | 750.00   | ?          |
| 51 | Radiator Fan Blade                     | ?          | 1     | 95.00    | ?          |
| 52 | Radiator Fan Clutch                    | ?          | 1     | 320.00   | ?          |
| 53 | Engine Mounting - LH & RH              | ?          | 2     | 120.00   | ?          |
| 54 | Coolant                                | ?          | 1     | 20.00    | ?          |
| 55 | Front Lower Arm - LH & RH              | ?          | 2     | 510.00   | ?          |
| 56 | Front Shock Absorber - LH & RH         | ?          | 2     | 560.00   | ?          |
| 57 | Front Wheel Hub c/w Bearing - LH & RH  | ?          | 2     | 760.00   | ?          |
| 58 | Front Knuckle Arm - LH & RH            | ?          | 2     | 510.00   | ?          |
| 59 | Front Upper Arm - LH & RH              | ?          | 2     | 810.00   | ?          |
| 60 | Front Anti Roll Bar                    | ?          | 1     | 255.00   | ?          |
| 61 | Front Anti Roll Bar Linkage - LH & RH  | ?          | 2     | 440.00   | ?          |
| 62 | Steering Rack & Pinion                 | ?          | 1     | 1,400.00 | ?          |
| 63 | Steering Cross Member                  | ?          | 1     | 1,280.00 | ?          |
| 64 | Rear Axle Wheel Hub - LH & RH          |            | 2     | 1,240.00 | ?          |
| 65 | Rear Storage Box Assy                  | Distorted  | 1     | 6,500.00 | 5500(S.N.) |

↓  
Please check if this item  
is insured . . .

|             |              |
|-------------|--------------|
| Sub Total   | 26,743.00    |
| Add 15%     | 4,011.45     |
| Total Parts | \$ 30,754.45 |

**S/NET ITEMS**

|   |                           |         |   |        |     |
|---|---------------------------|---------|---|--------|-----|
| 1 | Front Number Plate        | cut     | 1 | 25.00  | ✓   |
| 2 | Front Windscreen Sealant  | new     | 1 | 50.00  | ✓   |
| 3 | ERP Bracket               | new     | 1 | 25.00  | ✓   |
| 4 | Front Wheel Rim - LH & RH | LH Bent | 2 | 640.00 | 650 |
| 5 | Tyre - LH & RH            | new     | 2 | 720.00 | x   |
| 6 | Rear Wheel Rim - LH & RH  | Bent    | 2 | 640.00 | 500 |

**RE : ESTIMATE FOR ACCIDENT REPAIR GBK1026M (TOYOTA DYNA)**

|   |                         |   |             |    |
|---|-------------------------|---|-------------|----|
| 7 | Rear Tyre - LH & RH     | 2 | 720.00      | X. |
| 8 | Company Address Sticker | 2 | \$ 50.00    | 30 |
|   |                         |   | \$ 2,870.00 |    |

**Total Parts** \$ 33,624.45

**Labour Charge:**

|    |                                          |             |              |
|----|------------------------------------------|-------------|--------------|
| 1  | To knocking and renew above parts        | \$ 3,800.00 | 1609         |
| 2  | To putty and spray up paint work         | \$ 2,800.00 | 1600         |
| 3  | To check wiring system                   | \$ 100.00   | 50           |
| 4  | To apply tuff coat                       | \$ 300.00   | 200          |
| 5  | To transfer front LH & RH door fittings  | \$ 300.00   | 160          |
| 6  | To remove front windscreen               | \$ 180.00   | 120          |
| 7  | To remove cabin upholstery               | \$ 150.00   | 120          |
| 8  | To remove roof inner trim board          | \$ 200.00   | 150          |
| 9  | To remove dashboard                      | \$ 320.00   | ?            |
| 10 | To remove condenser & top up gas         | \$ 120.00   | 65           |
| 11 | To remove radiator & top up coolant      | \$ 120.00   | ?            |
| 12 | To dismantle front LH & RH undercarriage | \$ 850.00   | ?            |
| 13 | To dismantle rear LH & RH undercarriage  | \$ 400.00   | ?            |
| 14 | To perform wheel alignment               | \$ 150.00   | 80           |
| 15 | To remove rear storage box               | \$ 480.00   | ?            |
| 16 | To remove rear camera                    | \$ 100.00   | ?            |
| 17 | To remove rear video recorder            | \$ 100.00   | ?            |
| 18 | Towing fee                               | \$ 60.00    | ✓            |
|    |                                          |             | \$ 10,530.00 |

**Grand Total** \$ 44,154.45

GST Will be reflected in the final bills

**RE : ESTIMATE FOR ACCIDENT REPAIR GBK1026M (TOYOTA DYNA)**

**NOTE : -**

**PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.**

Adrian Lj  
1/s 21 Days  
Not Authorised,

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorised by Repairer