

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

idac

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8342A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DEFORMED	481.10	481.10
1	FRONT BUMPER UPPER MOULDING	NOT NECESSARY	368.50	-
10	FRONT BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	FRONT BUMPER SIDE BRKT LH	NOT NECESSARY	35.00	-
1	FRONT WHEEL CAP LH	NOT NECESSARY	346.40	-
1	FRONT FENDER LH	NOT NECESSARY	588.80	-
1	FRONT FENDER (BLUE-DRIVE) LH	NOT NECESSARY	26.60	-
1	FRONT FENDER SHIELD LH	NOT NECESSARY	164.70	-
1	HEADLAMP LH	NOT NECESSARY	2,110.30	-
1	DAYLIGHT LH	NOT NECESSARY	642.50	-
1	DAYLIGHT GRILLE LH	NOT NECESSARY	93.45	-
	LESS 20% DISCOUNT		-975.87	-100.62
			3,903.48	402.48
	SPECIAL NETT ITEMS			
1	FRONT FENDER ADV. STICKER LH (SN)	СИТ	100.00	100.00
			100.00	100.00
	<u>LABOUR</u>			
	PANEL BEATING.		800.00	350.00
	SPRAY PAINTING.		600.00	250.00
	CHECK WIRINGS.	NOT NECESSARY	40.00	-
	TUFF KOTE.	NOT NECESSARY	60.00	-
	WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
			1,620.00	600.00
	GRAND TOTAL		5,623.48	1,102.48





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	900.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)	

Report Ref No. NS/INC23006513/Tnp3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser