



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. AT 22U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FENDER FRONT	BROKEN	100.00	90.00
1	SEAT FRONT COVER	NOT NECESSARY	100.00	-
1	COVER SIDE 1	BROKEN	120.00	110.00
1	COVER SIDE 2	NECESSARY	120.00	110.00
1	COVER SIDE 3	CLIP BROKEN	100.00	80.00
1	BOARD FOOTREST	BROKEN	150.00	120.00
1	COVER 1	BROKEN	100.00	80.00
1	LEG SHIELD 1	BROKEN	120.00	110.00
1	LEG SHIELD 2	BROKEN	120.00	110.00
1	FENDER INNER	BROKEN	100.00	90.00
1	COVER UNDER 1	SCRATCHED	120.00	110.00
1	COVER UNDER 2	NECESSARY	100.00	90.00
1	PANEL INNER 1	BROKEN	110.00	100.00
1	COVER HEADLIGHT	NECESSARY	100.00	80.00
1	UNDER BRACKET COMP	NOT NECESSARY	360.00	-
1	SET FORK ASSY L/R	BENT	360.00	350.00
1	HANDLEBAR	OUT OF SHAPE	220.00	200.00
1	COVER HANDLEBAR UPPER 1	SCRATCHED	80.00	60.00
1	TAIL COVER	BROKEN	100.00	80.00
1	AIR DUCT	TORN	90.00	80.00
1	CRANKCASE UPPER COVER	BROKEN	150.00	130.00
1	BOX RACK	NOT NECESSARY	220.00	-
1	BOX	CRACKED	220.00	200.00
1	SET MIRRORS	DENTED	100.00	90.00
1	SET HANDLEBAR GRIPS	NOT NECESSARY	80.00	-
1	SET BAR BALANCER	DENTED	100.00	40.00
1	BRAKE LEVER	NOT NECESSARY	80.00	-
1	CLUTCH LEVER	SCRATCHED	80.00	60.00
	LESS 10% DISCOUNT		-380.00	-257.00
			3,420.00	2,313.00

Report Ref No. CS3/HSB23005042/Rnp3m4-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT LICENSE PLATE (SN)	REQUIRED	60.00	30.00
1	STEERING CONE (SN)	NECESSARY	300.00	85.00
			360.00	115.00
	<u>LABOUR</u>			
	REPLACE, REALIGN AND ADJUST ABOVE DAMAGED PARTS AND CHECK WIRING AND LIGHTNING SYSTEM.		1,100.00	200.00
	TO KNOCK, STRAIGHTEN CHASSIS AND BODY BALANCING.		1,100.00	150.00
	TO RESPRAY ON ACCIDENT AFFECTED AREA. (NPA)	NOT NECESSARY	-	-
	TOWING SERVICE.		150.00	80.00
			2,350.00	430.00
GRAND TOTAL			6,130.00	2,858.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,300.00

Report Ref No. CS3/HSB23005042/Rnp3m4-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.