

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS23006535/UQY3Q2**Date:** 31/07/2023**REFERENCE**

Insured/Claimant:	SGPETSHOP	Policy No:	MCV23B00006900	Claim No:	DMCV2300041H/ST
Date of Loss:	21/06/2023	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG1145Z		Engine No:	K9KC400D057001
Make & Model:	NISSAN NV200, 1.5 (M)		Chassis No:	VSKYBAM20Z0143749
Reg. Date:	31/05/2017 (Man. Year: 2016)		Odometer:	129220 km
Colour:	Blue			
Engine Capacity:	1461 cc			
Market Value/New Car Price:	S\$34,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,355.00	1,518.00	1,837.00	54.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,400.00	1,370.00	2,030.00	59.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,755.00	2,888.00	3,867.00	57.25
Approved Total (Overridden) (S\$)		2,300.00		
- Excess (S\$)	0.00	600.00	-600.00	
(S\$)	6,755.00	1,700.00	5,055.00	74.83
+ GST 8.00/8.00% (S\$)	540.40	136.00	404.40	74.83
Nett Amount (S\$)	7,295.40	1,836.00	5,459.40	74.83

INSPECTION

Date of Assignment:	28/06/2023	Present Location:	Automobile Integrated Management Pte Ltd (HQ)
Date Inspected:	05/07/2023	Inspected At:	Automobile Integrated Management Pte Ltd (HQ)
			1 Defu Lane 6
			Singapore 539365
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 28 Jul 2023)	
Parts:	N/A	NISSAN NV200 1.5 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG1145Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front bumper (WCP)	Distorted	340.00 F	*340.00 F
2	10		*FRONT BUMPER CLIPS (SN) (WCP)	Necessary	30.00 F	*30.00 F
3	1		*Front bumper tow cover (WCP)	Not Necessary	30.00 F	*- F
4	1		*FRONT BUMPER FOG LAMP (LH) (WCP)	Not Necessary	240.00 F	*- F
5	1		*FRONT BUMPER SIDE RETAINER (WCP)	Cracked	30.00 F	*30.00 F
6	1		*FRONT BUMPER SPONGE (WCP)	Not Necessary	390.00 F	*- F
7	1		*FRONT BUMPER REINFORCEMENT (WCP)	Not Necessary	420.00 F	*- F
8	1		*FRONT FENDER (WCP)	Buckled	300.00 F	*300.00 F
9	1		*FRONT FENDER INNER COWLING (WCP)	Torn	100.00 F	*100.00 F
10	10		*FRONT FENDER INNER COWLING CLIPS (WCP)	Necessary	30.00 F	*30.00 F
11	1		*BONNET (WCP)	Repair	500.00 F	*- F
12	1		*HEADLAMP (WCP)	Cracked	300.00 F	*300.00 F
13	1		*HEADLAMP BRACKET (WCP)	Cracked	60.00 F	*60.00 F
14	1		*HEADLAMP OUTER GARNISH (WCP)	No such part	90.00 F	*- F
15	1		*FRONT BUMPER SIDE COVER TOP (WCP)	Torn	190.00 F	*190.00 F

F=Franchise part.

		Sub Total (\$\$)	3,050.00	1,380.00
+ Margin on L,N Items 10.00/10.00% (\$\$)			305.00	138.00
		Total Parts (\$\$)	3,355.00	1,518.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	FENDER GLASS SEALANT	-	-
Sub Total (\$\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Remove, refix of parts and panel beating.	New	1,500.00	750.00
2	Spraypaint	New	1,500.00	600.00
3	Wiring	New	120.00	20.00
4	Rust proof coating	New	180.00	0.00
5	Fender glass	New	100.00	0.00
Gross Labour Cost (\$\$)			3,400.00	1,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >