

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/HLA23006536/UVY3Q2**Date:** 19/07/2023**REFERENCE**

Handling Insurer:	HL Assurance Pte Ltd	Policy No:	MP320699
Claimant Vehicle No :	SLK7048S	Insured Vehicle No :	SKV4897G
Date of Loss:	25/06/2023	Nature of Claim:	TP
		Claim No:	MPC04332

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK7048S	Engine No:	2ZR1766361
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	ZGE206031890
Reg. Date:	24/01/2017 (Man. Year: 2016)	Odometer:	62603 km
Colour:	Grey		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,271.32	611.15	2,660.17	81.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	720.00	1,080.00	60.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,071.32	1,331.15	3,740.17	73.75
Approved Total (Overridden) (S\$)		1,050.00		
(S\$)	5,071.32	1,050.00	4,021.32	79.30
+ GST 8.00/8.00% (S\$)	405.71	84.00	321.71	79.30
Nett Amount (S\$)	5,477.03	1,134.00	4,343.03	79.30

INSPECTION

Date of Assignment:	28/06/2023		
Date Inspected:	12/07/2023	Inspected At:	TLM Automobile Pte Ltd (HQ) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	2.0 days		

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Jul 2023)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK7048S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut / Deformed	703.20 F	*703.20 FL
2	1		*REAR BUMPER SIDE RETAINER	O/S Bent	90.00 F	*45.00 FL
3	1		*O/S REAR BUMPER RETAINER	Not Necessary	38.00 F	*- FL
4	1		*O/S REAR FENDER	Repair	520.00 F	*- FL
5	1		*O/S REAR WHEEL BEARING WITH HUB	Not Necessary	550.00 F	*- FL
6	1		*SET REVERSE SENSOR	Not Necessary	250.00 FS	*- FS
7	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
8	1		*O/S REAR SPORT RIM (CUT)	Not Consistent With The Impact	600.00 FS	*- FS
9	1		*O/S REAR TYRE	Not Necessary	280.00 FS	*- FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
Sub Total (\$\$)					3,081.20	798.20
- List Item Discount on L Items 0.00/25.00% (\$\$)					0.00	187.05
+ Margin on L,N Items 10.00/0.00% (\$\$)					190.12	0.00
Total Parts (\$\$)					3,271.32	611.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	20.00
2	TO TRANSFER OF O/S REAR TYRE ,RIM AND ON WHEEL BALANCING	New	60.00	0.00
3	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	80.00	0.00
4	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	800.00	300.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	800.00	400.00
Gross Labour Cost (S\$)			1,800.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >