

NCVI INVOLVING HIACE GBL1561D & CARPARK PILLAR ON 130623 AT AROUND 2145HRS AT HIGH STREET CENTRE MULTI-STOREY CARPARK




Figure A-1: Schematic of Incident




Figure A-2: Schematic of Incident




Figure A-3: Schematic of Incident



Figure B-1: Right Side View of GBL 1561D



Figure B-2: Left Side View of GBL 1561D



Figure B-3: Front View of GBL 1561D



Figure B-4: Rear View of GBL 1561D



Figure B-5: Damaged Rear RHS Tyre Rim



Figure B-6: Damage to Carpark Pillar

STATEMENT OF	CPL TAN BOON KIAT						ALIASES	N.A.		
NRIC NO	T209C	AGE	21				MALE/FEMALE	MALE		
EMPLOYMENT	NSF	DRIVING LICENCE NO	SAF/TPT/N/01309/22				NATIONALITY	SINGAPOREAN		
DIALECT	N.A.	LANGUAGE SPOKEN	ENGLISH				TEL NO			
ADDRESS										
INTERPRETED BY	N.A.	RANK	N.A.	TIME	N.A.	DATE	N.A.	SIGN	N.A.	
RECORDED BY	N.A.	RANK	N.A.	TIME	N.A.	DATE	N.A.	SIGN	N.A.	
<p>At around 2137H, we completed our MT-RAC and other checks were done. At 2145H, approval was given for us to move off. I excised my due diligence to check in checking both left and right side mirrors and warching for oncoming cars twice in making the turn out of the parking lot.</p> <p>Once I deemed it safe to moce out, I drove towards the carpark exit. As I turned my steering wheel right to execute the turn, I was looking at my mirrors to gauge the turning radius. In the process of my turn, I felt a momentary jerk and stopped the vehicle by pulling my parking brake and putting the vehicle to park. I stepped out of the vehicle investigate. I observed the light scratches on the right rear quarter panel as a result of contact with the caprak pillar.</p> <p>This incident was immediately reported to the conducting body including OC, PC and PSs. My VC took pictures of the scratches. No personnel and other equipment was injured or damaged.</p>										
DATE	130623	SIGNATURE OF DRIVER/WITNESS				<Sent via email>				

Figure C-1: Statement of TO

STATEMENT OF	3SG SABASTIAN TNEO						ALIASES	N.A.	
NRIC NO	T117D	AGE	20				MALE/FEMALE	MALE	
EMPLOYMENT	NSF	DRIVING LICENCE NO	N.A.				NATIONALITY	SINGAPOREAN	
DIALECT	N.A.	LANGUAGE SPOKEN	ENGLISH				TEL NO		
ADDRESS									
INTERPRETED BY	N.A.	RANK	N.A.	TIME	N.A.	DATE	N.A.	SIGN	N.A.
RECORDED BY	N.A.	RANK	N.A.	TIME	N.A.	DATE	N.A.	SIGN	NA
<p>At 2130H, CPL TAN BOON KIAT and 3SG SABASTIAN TNEO were preparing to return to unit after carrying out NDP comms trial which started from 0940H. The preparation included taking off the wheel choke, writing and entry for the MT-RAC. Following which, 3SG SEBASTIAN TNEO assessed CPL TAN BOON KIAT's fatigue level and deemed he was fit to drive before moving off.</p> <p>At 2145H, we prepared to drive back to unit, CPL TAN BOON KIAT checked his blind spots before driving out of the parking lot. CPL TAN BOON KIAT accidentally slightly scraped the right rear quarter panel of the HIACE against the parking lot pillar.</p> <p>As soon as CPL TAN BOON KIAT heard the faint sound of the car slightly scraping the pillar, he immediately braked the car and assessed the right rear quarter panel of the HIACE. It was observed that the paint of the HIACE was lightly scratched and the right wheel had small scratches.</p> <p>The incident was immediately reported to the conducting body involving OC and PC. No injuries were sustained by any personnel.</p>									
DATE	130623		SIGNATURE OF DRIVER/WITNESS			<Sent via email>			

Figure C-2: Statement of VC



 SINGAPORE POLICE FORCE		 A/20230615/7016		1 of 3	
POLICE REPORT (NP299) Police Station Of Origin Central Division HQ 391 New Bridge Road #03-112 Police Cantonment Complex SINGAPORE 088762 Tel No:1800-2240000		Report No. A/20230615/7016			
Date/Time Report Made 15/06/2023 11:58		Vide Report No.		Station Diary No.	
Name Of Informant TAN BOON KIAT		Address			
ID Type / ID No. NRIC NO / T 209C		Contact No. Home/Office: Mobile:			
Nationality SINGAPORE CITIZEN		Email Address			
Occupation National Service Full Time		Sex Male	Age 21	Date of Birth	Race Chinese
Institution/School Name		Language English			
Date/Time Of Incident 13/06/2023 21:45 - 13/06/2023 21:45		Location Of Incident 1 NORTH BRIDGE ROAD #4B HIGH STREET CENTRE SINGAPORE 179094			
Brief details.					
DV Statement for Vehicular Incident During NDP Communications Trial on 13 Jun 23					
HIACE Incident Report					
Carplate Number: GBL 1561D					
Time of Occurrence: 130623 2145H					
Signature Of Officer Recording The Report: Not applicable		Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.			
Signature Of Interpreter: Not applicable		Date/Time: 15/06/2023 11:58			
Officer In-Charge Of Case:		Classification Of Case:			

Figure C-3: Police Report Part 1



 SINGAPORE POLICE FORCE		 A/20230615/7016	2 of 3
POLICE REPORT (NP299)		CONTINUATION OF REPORT	
Report No. A/20230615/7016			
<p>Who was Involved:</p> <p>Dual Vocationalist: CPL TAN BOON KIAT</p> <p>Vehicle Commander: 3SG SABASTIAN TNEO</p>			
<p>What Happened:</p> <p>At around 2137H, we completed our MT-RAC and other checks were done. At 2145H, approval was given for us to move off. I exercised due diligence in checking both left and right side mirrors and watching for on coming cars twice in making the turn out of the parking lot.</p> <p>Once I deemed it safe to move out, I drove towards the carpark exit. As I turned my steering wheel right to execute the turn, I was looking at my mirrors to gauge the turning radius.</p> <p>In the process of my turn, I felt a momentary jerk and stopped the vehicle by pulling my parking brake and putting the vehicle to park. I stepped out of the vehicle to investigate. I observed light scratches on the right rear quarter panel as a result of contact with the carpark pillar.</p> <p>This incident was immediately reported to the conducting body indicating OC, PC and PSs. My VC took pictures of the scratches. No personnel and other equipment was injured or damaged.</p>			
<p>When did it happen:</p> <p>130623 2145H</p>			
Signature Of Officer Recording The Report: Not applicable		Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.	
Signature Of Interpreter: Not applicable		Date/Time: 15/06/2023 11:58	
Officer In-Charge Of Case:		Classification Of Case:	

Figure C-4: Police Report Part 2



 SINGAPORE POLICE FORCE		 <small>A/20230615/7016</small>	<small>3 of 3</small>
POLICE REPORT (NP299)		CONTINUATION OF REPORT	
Report No. A/20230615/7016			
<p>Where did it happen: Carpark 4B, High Street Centre Multi-Storey Carpark</p> <p>Why did it happen: Underestimation of turning radius in tight turns</p> <p>How did it happen: Early turn made due to underestimation of turning radius in executing the tight turn</p>			
Signature Of Officer Recording The Report: Not applicable		Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.	
Signature Of Interpreter: Not applicable		Date/Time: 15/06/2023 11:58	
Officer In-Charge Of Case:		Classification Of Case:	

Figure C-5: Police Report Part 3