

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/TMI23006556/KNP3Q2**Date:** 13/07/2023**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MP003255	
Claimant Vehicle No :	SHC5442P	Insured Vehicle No :	SFH73B	
Date of Loss:	24/06/2023	Nature of Claim:	TP	Claim No: M2303731

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5442P	Engine No:	2ZR2H01068
Make & Model:	TOYOTA PRIUS, 1.5 (A)	Chassis No:	JTDKB3FU203092189
Reg. Date:	15/04/2021 (Man. Year: 2020)	Odometer:	173092 km
Colour:	Metallic Pearl White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Wanli 8 mm	Rear Left Side:	Wanli 8 mm
Front Right Side:	Wanli 8 mm	Rear Right Side:	Wanli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,890.92	5,001.75	3,889.17	43.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,250.00	1,850.00	3,400.00	64.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,140.92	6,851.75	7,289.17	51.55
+ GST 8.00/8.00% (S\$)	1,131.27	548.14	583.13	51.55
Nett Amount (S\$)	15,272.19	7,399.89	7,872.30	51.55

INSPECTION

Date of Assignment:	05/07/2023	
Date Inspected:	27/06/2023	Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

Different 1 cents -Finalise confirm amount:\$6,851.76

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jul 2023)
Parts:	144	TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC5442P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,REAR BUMPER	Bent	612.68 FL	*612.68 FL
2	1		*COVER ,REAR BUMPER LOWER	Dented	27.93 FL	*27.93 FL
3	1		*GUARD ,REAR BUMPER CENTER	Bent	472.19 FL	*472.19 FL
4	1		*SEAL ,REAR BUMPER SIDE ,LH	Distorted	149.21 FL	*149.21 FL
5	1		*SEAL ,REAR BUMPER SIDE ,RH	Serviceable	149.21 FL	*- FL
6	1		*RETAINER ,REAR BUMPER SIDE ,LH	Distorted	167.48 FL	*167.48 FL
7	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	167.48 FL	*- FL
8	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Bent	419.90 FL	*419.90 FL
9	1		*REFLECRTOR ASSY ,REFLEX ,LH	Cut	49.25 FL	*49.25 FL
10	1		*REFLECRTOR ASSY ,REFLEX ,RH	Serviceable	49.25 FL	*- FL
11	1		*COVER ,REAR COMBINATION LAMP, RH	Serviceable	88.41 FL	*- FL
12	1		*LENS & BODY ,REAR COMBINATION LAMP ,RH	Serviceable	428.19 FL	*- FL
13	1		*LENS & BODY ,REAR COMBINATION LAMP ,NO.2 RH	Serviceable	329.49 FL	*- FL
14	1		*COVER ,REAR COMBINATION LAMP LH	Serviceable	88.41 FL	*- FL
15	1		*LENS & BODY ,REAR COMBINATION LAMP LH	Serviceable	428.19 FL	*- FL
16	1		*LENS & BODY ,REAR COMBINATION LAMP,NO.2 LH	Serviceable	329.49 FL	*- FL
17	1		*COVER ,FLOOR UNDER ,RH	Serviceable	220.50 FL	*- FL
18	1		*COVER ,FLOOR UNDER ,LH	Serviceable	304.92 FL	*- FL
19	1		*COVER ,REAR FLOOR	Missing	290.43 FL	*290.43 FL
20	1		*COVER ,DECK TRIM ,REAR	Serviceable	159.39 FL	*- FL
21	1		*PANEL SUB-ASSY ,BODY LOWER BACK	Bent	824.46 FL	*824.46 FL
22	1		*PANEL SUB-ASSY ,BACK DOOR	Bent	1,443.86 FL	*1,443.86 FL
23	1		*BOARD ,BACK DOOR TRIM	Serviceable	284.55 FL	*- FL
24	1		*PANEL ASSY ,BACK DOOR ,TRIM UPPER	Serviceable	65.73 FL	*- FL
25	1		*STAY ASSY ,BACK DOOR ,LH	Serviceable	305.66 FL	*- FL
26	1		*STAY ASSY ,BACK DOOR ,RH	Serviceable	305.66 FL	*- FL
27	1		*HINGE ASSY ,BACK DOOR ,LH	Repair	77.18 FL	*- FL
28	1		*HINGE ASSY ,BACK DOOR ,RH	Repair	77.18 FL	*- FL
29	1		*GARNISH SUB -ASSY ,BACK DOOR ,OUTSIDE	Mtg Cracked	1,156.89 FL	*1,156.89 FL
30	1		*PLATE ,LUGGAGE COMPARTMENT DOOR NAME NO.2	Necessary	68.88 FL	*68.88 FL
31	1		*PLATE BACK DOOR NAME NO.1	Necessary	68.88 FL	*68.88 FL
32	1		*ORNAMENT SUB-ASSY ,BACK DOOR	Necessary	90.30 FL	*90.30 FL
33	1		*SET PARKING AID	Dented	700.00 FS	*220.00 FS
34	1		*REAR BUMPER CLIP	Necessary	65.00 FS	*60.00 FS
35	1		*REAR RH BUMPER RETAINER CLIP	Not Necessary	65.00 FS	*- FS
36	1		*REAR LH BUMPER RETAINER CLIP	Not Necessary	65.00 FS	*- FS
37	1		*END PANEL INNER TRIM CLIP	Not Necessary	60.00 FS	*- FS
38	1		*REAR BUMPER PROTECTOR	Necessary	180.00 FS	*30.00 FS
39	2		*WINDSCREEN SEALANT	Necessary	150.00 FS	*80.00 FS
40	1		*WINDSCREEN MOULDING	Necessary	200.00 FS	*200.00 FS
41	1		*WINDSCREEN INNER SPONGE SEAL	Necessary	130.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)11,316.236,462.34

- List Item Discount on L Items 25.00/25.00% (\$\$)2,425.311,460.59

Total Parts (\$\$)8,890.925,001.75

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING OF THE AFFECTED AREAS	New	600.00	30.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,200.00	880.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,000.00	600.00
4	TO TRANSFER OF TAILGATE FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	60.00
5	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	60.00
6	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	170.00
7	TO TRANSFER OF TAILGATE FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
8	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
Gross Labour Cost (\$\$)			5,250.00	1,850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >