

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/TMI23006563/KVP3Q2**Date:** 06/07/2023REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MAA00172

Claimant Vehicle No : SHF620J**Insured Vehicle No :** SMN7056R

Date of Loss: 26/06/2023

Nature of Claim: TP Claim No: M2303796

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHF620J**

Make & Model: TOYOTA PRIUS, 1.8 (A)

Engine No: G4FGJH721700

Reg. Date: 28/01/2021 (Man. Year: 2020)

Chassis No: KNAF3416MK5041111

Colour: Metallic Pearl White/Red

Odometer: 165142 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car PriceCONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Wanli 9 mm

Rear Left Side: Sailun 6 mm

Front Right Side: Wanli 9 mm

Rear Right Side: Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,111.94	0.00	7,111.94	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,080.00	300.00	4,780.00	94.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,191.94	300.00	11,891.94	97.54
+ GST 8.00/8.00% (S\$)	975.36	24.00	951.36	97.54
Nett Amount (S\$)	13,167.30	324.00	12,843.30	97.54

INSPECTION

Date of Assignment: 04/07/2023

Date Inspected: 27/06/2023 Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
2, Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 1.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jul 2023)
Parts:	144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHF620J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,REAR BUMPER	Repair	612.68 FL	*- FL
2	1		*GUARD ,REAR BUMPER ,CENTER	Serviceable	472.19 FL	*- FL
3	1		*REFLECTOR ASSY ,REFLEX ,RH	Serviceable	49.25 FL	*- FL
4	1		*SEAL ,REAR BUMPER SIDE ,RH	Serviceable	149.21 FL	*- FL
5	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	167.48 FL	*- FL
6	1		*COVER FLOOR UNDER RH	Serviceable	220.50 FL	*- FL
7	1		*COVER ,REAR FLOOR	Serviceable	290.43 FL	*- FL
8	1		*COVER ,DECK TRIM ,REAR	Serviceable	159.39 FL	*- FL
9	1		*PANEL SUB-ASSY ,BODY LOWER BACK	Repair	824.46 FL	*- FL
10	1		*LENS & BODY ,REAR COMBINATION LAMP ,RH	Serviceable	428.19 FL	*- FL
11	1		*LENS & BODY ,REAR COMBINATION LAMP ,NO .2 RH	Serviceable	329.49 FL	*- FL
12	1		*COVER ,REAR COMBINATION LAMP RH	Serviceable	88.41 FL	*- FL
13	1		*PANEL SUB-ASSY ,QUARTER ,RH	Repair	1,099.46 FL	*- FL
14	1		*LINER ,REAR WHEEL ,HOUSE RH	Serviceable	176.09 FL	*- FL
15	1		*CAP ,WHEEL	Serviceable	266.91 FL	*- FL
16	1		*RIM	Serviceable	1,995.11 FL	*- FL
17	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
18	1		*REAR BUMPER CLIP	Not Necessary	65.00 FS	*- FS
19	1		*REAR LH BUMPER RETAINER CLIP	Not Necessary	65.00 FS	*- FS
20	1		*REAR RH BUMPER RETAINER CLIP	Not Necessary	65.00 FS	*- FS
21	1		*END PANEL INNER TRIM CLIP	Not Necessary	60.00 FS	*- FS
22	1		*REAR BUMPER PROTECTOR	Not Necessary	180.00 FS	*- FS
23	2		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
24	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	*- FS
25	1		*WINDSCREEN INNER SPONGE SEAL	Not Necessary	130.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,944.25	0.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,832.31	0.00
Total Parts (\$\$)	7,111.94	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING OF THE AFFECTED AREAS	New	600.00	0.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,200.00	220.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,000.00	80.00
4	TO TRANSFER OF TAILGATE FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
5	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
6	TO TRANSFER OF TAILGATE FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
7	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
8	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
9	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
Gross Labour Cost (S\$)			5,080.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >