

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD  
19 UBI ROAD 4  
SINGAPORE 408623  
TEL: 6490 9666 FAX: 6846 7483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0236/23

DATE : 26-JUN-2023

ALLIANZ INSURANCE SINGAPORE PTE LTD  
79 ROBINSON ROAD #09-01

S(068897)

TEL : 63954779/67143369

FAX : 63953768

ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : PRIMAC ENGINEERING P L - GIVEN 3 FREE SVC BY T8 EK

ADDRESS : 10 ANSON ROAD

#05-17

INTERNATIONAL PLAZA S(079903)

TELEPHONE NO : -

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM

POLICY NO : 7210055420-02

VEHICLE NO : GBD8255J

MODEL CODE : NV200 DX 1.6 A

MODEL/YEAR : NV200

ENGINE NO : HR16027482D

CHASSIS NO : VM20078574

MILEAGE : 141632 KM

DATE IN : 26/06/2023

LIABILITY : 0.00

EXCESS CLAUSE : 0.00

ESTIMATE BY : ELMER

ACCIDENT DATE : 26/06/2023

*- 9645 0084 elmer@fanchong.com*

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO GBD8255J

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOR CHARGES TO REPAIR BOTH RR FENDER, TRUNKFLOOR INNER RR END PANEL, RENEW TAIL GATE, RR BMPR AND	2340.00	
2	ZZ/002	OUTER RR END PANEL		
3	ZZ/003	CHARGES TO SPRAY PAINTING SAME	1250.00	
4	ZZ/004	REMOVE AND INSTALL REAR WINDSCREEN GLASS	190.00	
5	ZZ/005	REMOVE/INSTALL BOTH RR COMB LAMP /REPLACE IF DAMGE	80.00	
6	ZZ/006	APPLY SEALANT TO TAIL GATE AND REAR END PANEL OUTER @SGD\$100.00 EACH	200.00	
7	ZZ/007	REMOVE AND TRANSFER TAIL GATE MECHANISM	80.00	
8	ZZ/008	RENEW REVERSE SENSOR	110.00	
9	ZZ/009	COMPUTER CHECK DIAGNOSIS	120.00	
		TOTAL LABOUR CHARGES	4370.00	

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBD8255J

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMAR
1	CENTER FINISHER TAIL GATE	90810-JX30A	391.80		
2	LH RR COMB LAMP	26555-JX53A	280.60		
3	RH RR COMB LAMP	26550-JX00A	280.60		
4	EMBLEM-REAR VANNETTE	90892-JX00A	72.20		
5	EMBLEM-REAR NV200	90895-JX00A	105.00		
6	EMBLEM-REAR NISSAN	90890-JX00A	72.20		
7	SENSOR-REVERSE	SENSOR			250.00
8	REAR LICENCE PLATE	RLP			60.00
9	INNER RR END PANEL	75614-JX00A	641.30		
10	OUTER RR END PANEL	75617-JX00A	128.30		
11	70KM/H	70KM/H			15.00
12	LABEL-PAX6	PAX			15.00
13	LH STAY TAIL GATE	90451-JX00A	222.70		
14	RH STAY TAIL GATE	90450-JX00A	222.70		
15	SUNDRIES	NPN			50.00
16	REAR W/SCREEN SEALANT	SEALANT - 4			80.00
17	WEATHER STRIP TAIL GATE	90830-5LA0A	98.40		
18	TAIL GATE	K010M-JX0AB	1819.60		
19	TOW HOOK COVER RR BUMPER	85010-JX00A	15.70		
20	RH SIDE BRACKET RR BUMPER	85228-JX00A	41.50		
21	LH SIDE BRACKET RR BUMPER	85229-JX00A	41.50		
22	ENERGY ABSORBER RR BUMPER	85090-JX00A	104.70		
23	CLIP RR BUMPER @ SGD\$1.50 EACH	01553-05933	15.00		
24	REAR BUMPER	85022-5LA0B	1020.40		

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBD8255J

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMAR
	SUB TOTAL		5574.20	0.00	470.00
	LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		1114.84	0.00	0.00
	GRAND TOTAL		4459.36	0.00	470.00
	OVERALL TOTAL		4929.36		

LEGEND: REMARKS ( OK ) = APPROVED, REMARKS ( X ) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO GBD8255J

-----  
TOTAL LABOUR CHARGES                    4370.00  
TOTAL SPARE PARTS CHARGES            4929.36  
-----  
GRAND TOTAL                                9299.36 \*  
-----

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

-----  
NAME                                        :  
SURVEYED DATE                            :  
AUTHORIZED DATE                         :  
EXCESS CLAUSE                            :            0.00  
LIABILITY                                 :            0.00  
REMARKS                                    :

PLS NOTE : This estimate is based on visual inspection of the  
          affected vehicle. Should we require further labour  
          charges & spare parts in the process of repairs, we  
          shall inform you accordingly.