

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC6/AIG.23006585/4493

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

196N

Vehicle: IN / OUT

17A 811435

Veh No:

GBE 74564

Yr Regn:

21/03/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Kiaco 3.0DX cc 2982

Colour:

Red

A/C: Insured / Std / NI / NA

Sp. Reading

320634

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

195 R15 Austone

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

23/06/23

D.O.I.

3/7/23

Survey held at

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

fr O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27/7/23 2/5 \$1900 inform Susan

Date/Time, File Pass to?

☐

Preli. Report

☐

Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)



Liu's Brother Auto Engineering Workshop

No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883

UEN No: 53291793J

liusbro@gmail.com

Tel: 67411730

ESTIMATE

Name: AIG Asia Pacific Insurance Pte Ltd

Address Motor Claims Department

78 Shenton Way #07-16

AIG Building

Singapore 079120

Ref Date:

30-06-2023

Ref No:

GBE7456Y230623

Vehicle No:

GBE7456Y

Model / Make:

Toyota Hiace3.0 DX Diesel

Capacity: 2982 cc

Turbo MT 2WD LGV

Item #	Damaged Area	Description	Unit Price	Qty	Estimation / Quotation	N / SN	Cost Of Repair
1	Front	Bonnet	689.50	\$ 853.30	1	\$ 853.30	20
2		Bonnet "Toyota Logo" Motif	\$ 82.60	1	\$ 82.60		20
3		Head Lamp Rh	\$ 930.70	1	\$ 930.70		SN X
4		Grille Inner	\$ 138.80	1	\$ 138.80		CR
5		Grille Outer Lower	481.10	\$ 665.50	1	\$ 665.50	CR
6		Grille Clips	\$ 30.00	1	\$ 30.00	SN	12 X
7		Grille Outer Top	\$ 284.30	1	\$ 284.30		CR
8		Bumper	641.10	\$ 796.80	1	\$ 796.80	DE
9		Bumper Clips	\$ 65.00	1	\$ 65.00	SN	20 30 S/W
10		To check all wiring & electrical component for proper function	1252		\$ 30.00		20
11		Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc			\$ 400.00		300
12		To putty & spray painting & including touch up paint on accident affected areas			\$ 400.00		300
13		To apply Rust Proofing, reseal tuff coating treatment on accident area			\$ 30.00		✓

Total Parts & Labour of estimate for damaged vehicle

\$ 4,707.00

Total amount in Lumpsum Basis for repaired vehicle

SDL

Not Authorized
du
meru's
3/7/23
L/S # 1900
4 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Liu's Bro Auto Engrg Wks

P-2317-4
252
1738.05
30
650
2418.05
22
1934