



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBV 6476G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	UNBEKANNT LHR BUMPER BRACKET (SIDE) (SN)	NOT NECESSARY	48.60	-
1	GUIDE PROFILE RHS RHR BUMPER BRACKET (SIDE) (SN)	NOT NECESSARY	48.60	-
4	SEAL RING SATIN BLACK (SN)	NECESSARY	24.40	24.40
1	SENSOR PRIMED (SN)	NOT NECESSARY	194.63	-
1	UNBEKANNT LHR REFLECTOR (SN)	NOT NECESSARY	61.29	-
1	UNBEKANNT REAR LOWER SPOILER (SN)	NOT NECESSARY	273.69	-
			651.21	24.40
<b>LABOUR</b>				
	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR.	NOT NECESSARY	280.00	-
	B&P DIAGNOSIS AND PROGRAMMING.		480.00	480.00
	LABOUR.		2,520.00	840.00
	SPRAY PAINTING.		2,400.00	800.00
			5,680.00	2,120.00
<b>GRAND TOTAL</b>			<b>6,331.21</b>	<b>2,144.40</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>2,144.40</b>

Report Ref No. CS/SMR23006586/Rqp3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.