

Registration no. 201936325M

28th June 2023

To : whom it may concern

Re : Estimated repair for KTM 1290 SUPERDUKE GT (FBL18M)

1.	Headlight Assy	\$890.00 crap
2.	Front Fender	\$450.00 out
3.	LH Cover Headlight	\$120.00 wt
	LH Front Cowling Cover Upper	\$80.00 mt/
	LH Fairing x 2	\$788.00 cut
	LH Signal	\$98.00 (00)
	LH Cornering Light	\$588.00 ?
	Radiator Assy	\$950.00🗶
	Crash Bar powerparts	\$700.00 叶ノ
	Handle Bar	\$430.00 7
	Handle Bar Balancer	\$80.00 00
	Front Windshield	\$280.00 (~~/
	Winshield holder	\$198.00 MY/
	LH Clutch Master Pump Assy	\$750.00 X
	LH Front Brake Disc	\$550.00 %
		\$880.007
	Steering Stem Lower	\$500.00 200 phoh
	LH Fork repair	\$100.00
	Transport	\$280.00 }
	Storage (14 days)	
20.	Labour Charge (20 hours)	\$700.00 500

Tanfilmi 97495749
31712303pm.
tanfilmi e lihlandonum.
Hdays
114 Resurvey after nepair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurve, before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

8 Kaki Bukit Ave 4 #03-03 Premier@Kaki Bukit Singapore 415875 Contact: 65 88228789